

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 May 2022

Preliminary Advice

Insured	: SKR835H		
Vehicle No			
TP Vehicle		Accident Date	: 23/04/2022
No	: SLP1187L		
Make	: OPEL CORSA	Assignment Date	: 05/05/2022
Date of	: 28/04/2022	Est. Duration of	: 2
Inspection		Repair	
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ)		
	23 KAKI BUKIT AVE 4, #04-01		
	SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,725.20
Revised Amount	:S\$	3,144.50
Check Items (Estimated)	:S\$	1,734.30
Total	:S\$	4,878.80

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.