



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

not authorized
see
27/4/22
1/5 \$4350
5 ty.

QUOTATION

No : QT-000285

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#03-03 SINGAPORE LAND TOWER
 SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555

FAX : 62213302

Your Ref. : FBR3907X
 Vehicle No. : SLF7648L
 Make & Model : HONDA VEZEL
 Chasis No. : RU11205077
 Engine No. : L15B4405098
 Accident Date : 26-04-2022
 Policy No. : 5083884730-05
 Date : 29-04-2022
 Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BOOT <i>997-60</i>	<i>3 only</i> 1.0	PCS 1,459.10	1,459.10
2	WINDSCREEN MOULDING (REAR)	<i>1</i> 1.0	PCS 82.10	82.10
3	LOGO "H"	<i>1</i> 1.0	PCS 32.30	32.30 X
4	EMBLEM "VEZEL"	<i>5</i> 1.0	PCS 68.70	68.70 X
5	REAR BOOT GARNISH	<i>1</i> 1.0	PCS 252.10	252.10 X
6	LAMP (NUMBER PLATE)	<i>1</i> 2.0	PCS 42.50	85.00 X
7	LAMP (R/H/R)	<i>1</i> 1.0	PCS 547.30	547.30 X
8	LAMP (REAR) (R/H)	<i>1</i> 1.0	PCS 354.80	354.80 X
9	REAR BOOT INNER TRIM BOARD	<i>2</i> 1.0	PCS 217.90	217.90
10	REAR BOOT INNER TRIM BOARD CLIPS	<i>1</i> 12.0	PCS 4.50	54.00
11	REAR BOOT ADJUSTER RUBBER	<i>1</i> 2.0	PCS 9.20	18.40 X
12	REAR BOOT INNER LOCK	<i>3</i> 1.0	PCS 224.60	224.60
13	REAR BOOT LOCK STRIKER	<i>1</i> 1.0	PCS 26.10	26.10 X
14	REAR BOOT WEATHERSTRIP	<i>1</i> 1.0	PCS 125.60	125.60 X
15	REAR END PANEL	<i>2</i> 1.0	PCS 762.40	762.40 X
16	REAR BUMPER <i>78</i>	<i>1</i> 1.0	PCS 980.00	980.00
17	BUMPER CLIP	<i>1</i> 6.0	PCS 4.50	27.00
18	BUMPER SIDE RETAINER (R/H/R)	<i>1</i> 1.0	PCS 19.50	19.50 X
19	BUMPER <i>lower under cover</i>	<i>1</i> 1.0	PCS 362.60	362.60
20	PROTECTOR (FENDER) ARCH (R/H/R)	<i>1</i> 1.0	PCS 165.00	165.00 X
21	REAR BUMPER REFLECTOR (R/H)	<i>1</i> 1.0	PCS 81.60	81.60
22	EXHAUST MUFFLER	<i>1</i> 1.0	PCS 602.40	602.40
23	EXHAUST MOUNTING	<i>2</i> 2.0	PCS 17.60	35.20
24	Discount 20 % ✓			-1,316.74
25	SubTotal (L)			5,266.96
26	REAR BUMPER LIP <i>lower</i>	<i>1</i> 1.0	PCS 800.00 <i>500</i>	800.00
27	REAR BUMPER CHROME MOULDING (REFLECTOR) (R/H)	<i>1</i> 1.0	PCS 150.00 X	150.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000285

SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #03-03 SINGAPORE LAND TOWER
 SINGAPORE 048623
 Attn: Motor Claims Department
 TEL : 64616555 FAX : 62213302

Your Ref. : FBR3907X
 Vehicle No. : SLF7648L
 Make & Model : HONDA VEZEL
 Chasis No. : RU11205077
 Engine No. : L15B4405098
 Accident Date : 26-04-2022
 Policy No. : 5083884730-05
 Date : 29-04-2022
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
28	REAR BOOT LOWER CHROME MOULDING	<i>inf</i> 1.0	PCS 450.00 <i>300</i>	450.00
29	REAR BOOT GARNISH (CHROME)	<i>11</i> 1.0	PCS 450.00 X	450.00
<i>Rear</i> 30	SEALANT (WINDSCREEN)	<i>1ea</i> 1.0	PCS 50.00 <i>40</i>	50.00
31	REAR NUMBER PLATE	<i>11</i> 1.0	PCS 35.00 X	35.00
<i>Rear</i> 32	REVERSE SENSOR	<i>shorts</i> 1.0	SET 280.00 <i>200</i>	280.00
33	SubTotal (S)			2,215.00
34	PANEL BEAT & REPAIR REAR DAMAGE	1.0	X <i>520</i> 1,000.00	1,000.00
35	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X <i>80</i> 120.00	120.00
36	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	X <i>20</i> 80.00	80.00
37	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X <i><</i> 50.00	50.00
38	TO CHECK AND REPAIR WATER LEAKING	1.0	X <i>11</i> 120.00 X	120.00
39	TO TRANSFER REAR BOOT FITTING	1.0	X <i>60</i> 120.00	120.00
40	TO REMOVE REVERSE SENSOR	1.0	X <i>50</i> 80.00	80.00
41	TO PROVIDE UNDER TURFCOAT	1.0	X <i>30</i> 150.00	150.00
42	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X <i>700</i> 900.00	900.00
43	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X <i>120</i> 150.00	150.00
44	TO REMOVE AND REPLACE DAMAGED EXHAUST SYSTEM	1.0	X <i>60</i> 120.00	120.00
45	SubTotal (Labour)			2,890.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000285

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#03-03 SINGAPORE LAND TOWER

SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555

FAX : 62213302

Your Ref. : FBR3907X
 Vehicle No. : SLF7648L
 Make & Model : HONDA VEZEL
 Chasis No. : RU11205077
 Engine No. : L15B4405098
 Accident Date : 26-04-2022
 Policy No. : 5083884730-05
 Date : 29-04-2022
 Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
------	-------------	-----	-----------------	---------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE DOLLAR TEN THOUSAND THREE HUNDRED SEVENTY ONE AND CENTS NINETY SIX ONLY

E. & O.E

Total	S\$	10,371.96
Discount	S\$	0.00
Net Total	S\$	10,371.96

Customer's Signature/Co. Stamp

ZERO GRAVITY

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise if is assumed that this bill is accepted as correct.

P-3470
 20%
 2-2776
 S.N-1040
 2-1640
 4458
 4364