

ASS. REC. BY:

REP:

CS/AIS 22003942/ Any3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLW3441C Yr Regn: 2018 / Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra. c.c. 1591Colour: Blue. A/C: Insured / Std / NI / NASp. Reading: 245335 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMH D841CMJU62\*8366.Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ariyo.

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 26/04/22Survey held at Premium Carz.Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Allianz.</u>
	<u>14/7/22 Lump Sum \$ 8850 and 11 days</u>
	<u>MV: (Red, \$ 11,243.60, 56%)</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?



Preli. Report

1) 14/7/22

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 11Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Client

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Report Format:

TP

Lump Sum L.P.T. \$

8850



Co. Reg. No.: 201416720C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel: 6636 9100 Fax: 6636 9113

Date : 25/04/2022

TO: Allianz Insurance Singapore Pte Ltd  
79 Robinson Road  
#09-01  
Singapore 068897

Attn : Motor Claims Department  
Email : claims@allianz.com.sg

Our Customer : Stephen John Lee Yew Cheng

Vehicle No : SLW3441C

Model : Hyundai Elantra

Manufacture Year : 2018

Date of Accident : 23/04/2022

Total Estimate Repair Days : 15

Total Pages : 3

KMH D841CMJU 628366

Re: Repair Estimate For Third Party Claim against SLX1702H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks Fr Surveyor
A.	Spare Parts				
1	Rear bumper Distorted	1	\$561.80	\$561.80	✓ 495
2	Rear bumper side retainer RH Not nec	1	\$54.00	\$54.00	×
3	Rear bumper side retainer LH Damaged	1	\$54.00	\$54.00	✓
4	Rear bumper reflector LH Not	1	\$79.00	\$79.00	✓
5	Rear bumper harness wiring Not nec	1	\$235.00	\$235.00	×
6	Rear bumper pad Distorted	1	\$350.10	\$350.10	✓ 265
7	Rear bumper reinforcement Not nec	1	\$394.80	\$394.80	×
8	Rear end panel Repair	1	\$452.00	\$452.00	R
9	Rear end panel garnish Not nec	1	\$99.80	\$99.80	×
10	Rear fender LH Distorted	1	\$1,892.00	\$1,892.00	✓
11	Rear fender inner trim LH Crumpled	1	\$207.00	\$207.00	✓
12	Rear fender inner shield LH Deformed	1	\$95.00	\$95.00	✓
13	Rear mudflap LH Not	1	\$49.60	\$49.60	✓
14	Petrol cover Dented	1	\$125.00	\$125.00	✓
15	Air vent LH Deformed	1	\$59.00	\$59.00	✓
16	Rear under cover LH Deformed	1	\$115.00	\$115.00	✓
17	Rear wheelhouse panel LH Repair	1	repair	repair	×
18	Rear windscreen moulding Not	1	\$95.00	\$95.00	✓
19	Tail lamp LH Deformed	1	\$462.60	\$462.60	✓
20	Tail lamp panel LH Dented	1	\$165.00	\$165.00	✓
21	Tail lamp clip Not	4	\$15.00	\$60.00	10
22	Boot lid Repair	1	\$1,782.00	\$1,782.00	×
23	Boot lid lock	1	\$245.00	\$245.00	×
24	Boot lid weatherstrip Not	1	\$172.50	\$172.50	×
25	Boot lid hinges Not	2	\$65.00	\$130.00	×
26	Boot lid reflector LH Not	1	\$284.90	\$284.90	✓
27	Boot lid "Hyundai" logo Not	1	\$65.00	\$65.00	✓
28	Boot lid "Elantra" emblem Not	1	\$58.00	\$58.00	✓



# Premium Carz


Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
29	Boot lid "S" emblem <i>nee</i>	1	\$38.00	\$38.00	✓
30	Boot lid inner trim <i>nee</i>	1	\$190.00	\$190.00	✗
31	Rear absorber LH <i>Bent</i>	1	<del>\$380.00</del>	<del>\$380.00</del>	✓
32	Rear axle <i>nee</i>	1	\$1,289.00	\$1,289.00	✗
33	Rear wheel hub bearing LH <i>damaged</i>	1	\$375.00	\$375.00	✓
34	Rear door LH <i>Dented</i>	1	\$1,157.00	\$1,157.00	✓
35	Rear door outer handle LH, chrome <i>nee</i>	1	\$195.00	\$195.00	✗
36	Rear door lock LH <i>nee</i>	1	\$197.00	\$197.00	✗
37	Rear door weathstrip LH <i>nee</i>	1	\$171.20	\$171.20	✗
38	Rear door trimboard LH <i>nee</i>	1	\$756.00	\$756.00	✗
39	Rear door power window regulator LH <i>2nd</i>	1	\$245.00	\$245.00	✗
40	Rear door power window regulator motor LH <i>nee</i>	1	\$358.00	\$358.00	✗
41	Rear door black sash pillar sticker LH <i>nee</i>	1	\$45.00	\$45.00	✓
42	Rear door hinge <i>3rd</i>	2	\$58.00	\$116.00	✗
43	Rear door striker <i>3rd</i>	1	\$45.00	\$45.00	✗
44	Rocker panel LH <i>4th</i>	1		\$0.00	✗
45	Front door LH <i>Distorted</i>	1	\$1,177.00	\$1,177.00	✓
46	Front door outer handle LH, chrome <i>4th</i>	1	\$195.00	\$195.00	✓
47	Front door lock LH <i>Damaged</i>	1	<del>\$197.00</del>	<del>\$197.00</del>	✓
48	Front door weathstrip LH <i>5th</i>	1	\$171.20	\$171.20	✗
49	Front door trimboard LH <i>5th</i>	1	\$756.00	\$756.00	✗
50	Front door power window regulator LH <i>Damaged</i>	1	\$245.00	\$245.00	✓
51	Front door power window regulator motor LH <i>6th</i>	1	\$358.00	\$358.00	✗
52	Front door black sash pillar sticker LH <i>nee</i>	1	\$45.00	\$45.00	✓
53	Front door sensor switch LH <i>nee</i>	1		\$0.00	✗
54	Side mirror LH <i>Damaged</i>	1	\$638.00	\$638.00	✓
55	Side mirror cover LH <i>7th</i>	1	\$135.00	\$135.00	✗
56	Side mirror signal lamp LH <i>cut</i>	1	\$127.00	\$127.00	✓
				<b>Total</b>	<b>\$17,844.50</b>
				Less 20%	<b>\$3,568.90</b>
				<b>Sub Total 1</b>	<b>\$14,275.60</b>
<b>B.</b>	<b>Spare Parts (S/Nett)</b>				
1	Rear bumper clip <i>nee</i>	10	\$4.00	\$40.00	30
2	Rear end panel garnish clip <i>nee</i>	7	\$4.00	\$28.00	✗
3	Rear door trimboard clip <i>nee</i>	10	\$4.00	\$40.00	✗
4	Rear fender inner trim clip <i>3rd</i>	10	\$4.00	\$40.00	30
5	Rear fender inner shield clip <i>5th</i>	10	\$4.00	\$40.00	10
6	Boot lid inner trim clip <i>nee</i>	10	\$4.00	\$40.00	✗
7	Front door trimboard clip <i>8th</i>	10	\$4.00	\$40.00	✗
8	Rear tyre LH <i>nee</i>	1	\$450.00	\$450.00	✗
9	Rear sports rim LH <i>cut</i>	1	\$550.00	\$550.00	400
10	Sealant <i>nee</i>	1	\$60.00	\$60.00	✓



Co. Reg. No.: 201416720C  
1 Kaki Bukit Av 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel: 6636 9100 Fax: 6636 9113

Adrian Cij  
t/s 26/04/22  
11 Days.

7 Teng  
Premium Carz Services Pte Ltd

total: 11056.08

H/S: 8850

Acknowledged by Repairer  
Signature:  
Date: