

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

ESTIMATE

Date : 25th April 2022

Mr **Chiew Beng Hock**

Blk 128C Punggol Field Walk, #08-315
Singapore 823128

Veh No : **SJR 8239M**

Make/Model : **Mit Lancer**

Chassis No : JMYSRCY2A9U004331

Date of Acc : 25.04.22

TP Veh No : SMF 6981T

S/No	Qty	Description	Unit Price	Amount
Materials (Nett)				
1	1 pc	Rear Boot Lid		
2	1 pc	Rear Boot Lid Logo	\$ 782.00	x
3	1 pc	Rear Boot Lid Mechanism Lock	\$ 45.00	x
4	1 pc	Rear Lamp LH	\$ 212.00	x
5	1 pc	Rear Bumper	\$ 475.20	x
6	1 pc	Rear Bumper Side Holder LH	\$ 968.20	x
7	1 pc	Rear Bumper Reflector LH	\$ 52.00	x
8	1 pc	Rear Bumper Tow Hook Cover	\$ 42.00	x
9	1 pc	Rear Bumper Reinforcement	\$ 43.20	x
10	1 pc	Rear Boot Weatherstrip	\$ 223.30	x
11	1 pc	Rear End Panel	\$ 196.00	x
12	1 pc	Rear End Panel Top Garnish	\$ 592.00	x
13	1 pc	Spare Tire Panel	\$ 163.30	x
14	1 pc	Spare Tire Panel Cover	\$ 836.00	x
			\$ 236.30	x
			\$ 4,866.50	
		Less 10%	\$ 486.65	
		Parts Total :	\$ 4,379.85	

Special Nett				
1	1 pc	Rear Bumper Lower Spoiler		
2	1 set	Rear Bumper Clips	\$ 650.00	x
3	1 set	End Panel Top Garnish Clips	\$ 45.00	x
4	1 set	Reverse Sensor	\$ 35.00	x
5	1 set	Rear License Plate w/Frame	\$ 250.00	x

Special Nett : \$ 1,030.00

Labour				
1		To remove & rearrange electrical wirings, check lightings	\$ 80.00	15L
2		To remove & replace upholstery, trim garnishes to facilitate repairs.	\$ 100.00	60L
3		To remove, transfer boot lid components	\$ 80.00	x
4		To remove, repair & replace damaged bodyparts and where consistent to the accident.	\$ 800.00	550L
5		Putty and respray painting on affected portions	\$ 1,000.00	600L
6		To remove & renew reverse sensor	\$ 100.00	50L
7		Rust proofing on affected portions.	\$ 100.00	30L


Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


for E M Solution Pte Ltd

TOTAL

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K


Supplementary

Date : 27th April 2022

Mr **Chiew Beng Hock**
Blk 128C Punggol Field Walk, #08-315
Singapore 823128

Veh No : **SJR 8239M**
Make/Model : **Mit Lancer**
Chassis No : JMYSRCY2A9U004331
Date of Acc : 25.04.22
TP Veh No : SMF 6981T

S/No	Qty	Description	Unit Price	Amount
Materials (Nett)				
1	1 pc	Rear Bumper Top Beam		\$ <i>Bz</i> 105.60
2	1 pc	Rear Fender Liner LH		\$ <i>CM</i> 128.00
				\$ 233.60
Less 10%				\$ 23.36
Parts Total :				\$ 210.24



for E M Solution Pte Ltd

TOTAL