

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003956/AQY3M4**Date:** 22/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00044922102
Claimant Vehicle No :	GBD2061R	Insured Vehicle No :	YN319L
Date of Loss:	19/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202861/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD2061R	Engine No:	263A50007155205
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 (M)	Chassis No:	ZFA26300006167058
Reg. Date:	29/07/2014 (Man. Year: 2014)	Odometer:	121302 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16C	Rear Tyre Size:	195/60 R16C
Front Left Side:	ANNAITE 6 mm	Rear Left Side:	ANNAITE 6 mm
Front Right Side:	ANNAITE 6 mm	Rear Right Side:	ANNAITE 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,783.68	3,259.98	1,523.70	31.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,040.00	810.00	43.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,633.68	4,299.98	2,333.70	35.18
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	6,633.68	3,400.00	3,233.68	48.75
+ GST 7.00/7.00% (S\$)	464.36	238.00	226.36	48.75
Nett Amount (S\$)	7,098.04	3,638.00	3,460.04	48.75

INSPECTION

Date of Assignment:	27/04/2022	
Date Inspected:	28/04/2022	Inspected At: KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2022)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD2061R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Distorted	2,100.00 FL	*1,472.00 FL
2	1		*FRONT DOOR SIDE MIRROR LH	Cracked	580.20 FL	*580.20 FL
3	1		*FRONT DOOR SIDE MIRROR LAMP	Cracked	155.00 FL	*155.00 FL
4	1		*FRONT DOOR PROTECTOR	Not Necessary	200.00 FL	*- FL
5	1		*FRONT DOOR STICKER	Necessary	55.00 FL	*55.00 FL
6	1		*FRONT DOOR OUTER MOULDING	Deformed	250.00 FL	*250.00 FL
7	1		*FRONT DOOR HINGE TOP	Bent	190.00 FL	*190.00 FL
8	1		*FRONT DOOR HINGE LOWER	Not Necessary	190.00 FL	*- FL
9	1		*FRONT DOOR INNER LOCK	Not Necessary	380.00 FL	*- FL
10	1		*FRONT FENDER	Dented	620.00 FL	*620.00 FL
11	1		*FRONT DOOR OUTER HANDLE	Cut	300.00 FL	*300.00 FL
12	10		*FRONT DOOR INNER RUBBER	Not Necessary	295.00 FL	*- FL
					Sub Total (\$\$)	5,315.20 3,622.20
					- List Item Discount on L Items 10.00/10.00% (\$\$)	531.52 362.22
					Total Parts (\$\$)	4,783.68 3,259.98

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY	New	780.00	500.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	850.00	450.00
3	TO REMOVE UPHOLSTERY	New	120.00	60.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	30.00
Gross Labour Cost (S\$)			1,850.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >