

ASS. REC. BY: Tauyph

REF:

CE/AGL22003957/Try3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMN 8194T

Policy No. _____


Claims No. C10014918

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 958K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR: Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

- WP'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLM 520E Yr Regn: 2017, MarchType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Florida City 1-5 c.c. 1497Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 145792 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHGM 6660-4P000556Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R16R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WestlakeFront 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/4/2022 D.O.I. 28/4/22Survey held at TSC AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/1/23 Lump Sum \$6750 confirmed with Ah Long (red 11,167.28, 62%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 6/1/23-typist

Days Of Repair: 9Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Rep. Format: TPLump Sum / L.B. / P. \$6750

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

			Estimated	
No	Qty	Parts Description	Parts Price	
1	1	Rear bumper assy	\$ 589.70	de 464 ✓
2	2	Rear bumper bracket	\$ 39.60	de ✓
3	2	Rear bumper side retainer	\$ 37.40	de ✓
4	2	Rear bumper reflector	\$ 189.60	cu 68 ✓
5	1	Rear bootlid assy	\$ 683.40	bt ✓
6	2	Rear bootlid rubber stopper	\$ 36.30	x nn
7	2	Rear bootlid hinges	\$ 125.70	x nn
8	1	Rear bootlid weatherstrip	\$ 167.90	cut ✓
9	1	Rear bootlid lock mechanism	\$ 105.40	bt ✓
10	1	Rear bootlid lock catch	\$ 67.40	x nn
11	1	Rear bootlid centre logo	\$ 68.30	de ✓
12	1	Rear bootlid city emblem	\$ 56.80	de ✓
13	1	Rear bootlid IVTEC emblem	\$ 48.30	de ✓
14	1	Rear bootlid outer chrome garnish	\$ 176.20	x nn
15	1	Rear bootlid inner board	\$ 172.60	x nn
16	1	Rear left bootlid taillamp	\$ 212.80	cut ✓
17	1	Rear right bootlid taillamp	\$ 212.80	cut ✓
18	1	Rear left taillamp	\$ 446.20	cu ✓
19	1	Rear right taillamp	\$ 446.20	cu ✓
20	1	Rear end lower panel	\$ 480.60	bt ✓
21	1	Rear end lower panel top garnish	\$ 88.10	de ✓
22	2	Rear no plate lamp	\$ 88.00	x nn
23	1	Rear floor panel	\$ 880.90	bul ✓ 560 ✓
24	1	Rear spare tyre top board	\$ 168.50	cu ✓
25	1	Rear exhaust muffler assy	\$ 951.50	x R
26	2	Rear exhaust muffler rubber mounting	\$ 36.30	x nn
			\$ 6,576.50	4354.30
Less 20%			\$ 1,315.30	-20%
			\$ 5,261.20	3483.44

Special Nett Items

1	10	Rear bumper clips	\$ 50.00	30 ✓
2	8	Rear bootlid inner board clips	\$ 30.00	x nn
3	4	Rear bootlid outer chrome garnish clips	\$ 30.00	x nn
4	4	Rear end lower panel top garnish clips	\$ 30.00	20 ✓
5	1	Rear end lower panel sealant	\$ 120.00	40 ✓
6	1	Rear floor panel sealant	\$ 120.00	x nn
7	1	Rear floor panel insulator pad	\$ 150.00	10 ✓
8	4	Rear bumper reverse sensor	\$ 600.00	20 ✓
9	1	Rear view camera	\$ 450.00	x nn
10	1	Rear no plate with garnish	\$ 100.00	x nn
			\$ 1,680.00	390

Total parts

\$ 6,941.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	\$ 589.90	de ✓
2	1	Front bumper left bracket	\$ 66.30	de ✓
3	1	Front bumper right bracket	\$ 66.30	x nn
4	1	Front bumper left side retainer	\$ 63.20	de ✓
5	1	Front bumper right side retainer	\$ 63.20	x nn
6	1	Front grille assy	\$ 296.80	one ✓ 186 ✓
7	1	Front grille emblem	\$ 68.60	nn ✓
8	1	Fron bumper lower grille assy	\$ 193.50	x nn
9	1	Front bonnet assy	\$ 792.40	x nn
10	1	Front bonnet insulator	\$ 128.20	x nn
11	1	Front right headlamp	\$ 428.30	one ✓
12	1	Front left headlamp	\$ 428.30	one ✓
13	1	Front right headlamp bracket	\$ 68.00	x nn
14	1	Front left headlamp bracket	\$ 68.00	x nn
15	1	Front support panel assy	\$ 492.80	x R
16	1	Front support panel top garnish	\$ 179.10	x nn
17	1	Front bonnet lock mechanism	\$ 155.70	x nn
18	1	Front bumper tow cover	\$ 68.80	x nn
19	1	Front bumper reinforcement	\$ 311.50	x nn
20	1	Front left fog lamp	\$ 252.10	one ✓
21	1	Front right fog lamp	\$ 252.10	x nn
22	1	Front left fog lamp cover	\$ 68.50	x nn
23	1	Front right fog lamp cover	\$ 68.50	x nn
			\$ 5,170.10	2082.70
Less 20%			\$ 1,034.02	-20%
			\$ 4,136.08	1666.16

Special Nett Items

1	10	Front bumper clips	\$ 50.00	30 rec
2	4	Front grille clips	\$ 20.00	10 rec
3	1	Front no plate with garnish	\$ 100.00	x nn
4	1 set	Front bumper lower grille clips	\$ 40.00	x nn
5	6	Front support panel top garnish clips	\$ 30.00	x nn
6	1 set	Front bonnet insulator clips	\$ 40.00	x nn
			\$ 280.00	40

Total parts

\$ 4,416.08

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,000.00 400 300
2	To putty and spray painting front portion.	\$ 1,000.00 400 300
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To apply anti rust proofing to front affected area.	\$ 140.00 X
6	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 000
7	To putty and spray painting rear portion.	\$ 1,400.00 900
8	To check rear lighting and wiring.	\$ 50.00 30
9	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
10	To remove and install rear exhaust muffler assy.	\$ 120.00 60
11	To repair straighten and align both rear fenders.	\$ 350.00 X
12	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 60
13	To apply anti rust proofing to rear affected area.	\$ 140.00 40
14	To remove and install rear view camera.	\$ 80.00 30
15	To remove and install rear bumper reverse sensor.	\$ 80.00 30
16	To conduct chassis alignment.	\$ 350.00 X
17	Towing service.	\$ 100.00 X
Total labour :		\$ 6,560.00 2840

Total parts : \$ 11,357.28 8419.60

Total labour : \$ 6,560.00

Total repair cost : \$ 17,917.28 L/S - 6735.68 = 6750

Tanpin 97495749
 WP 28/4/22 @ 320pm.
 1/2 Resurvey after repair
 tanpin @ lkkauto.com
 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____