

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

			Estimated Parts Price	
No	Qty	Parts Description		
			\$	589.70 <i>de</i> 464 ✓
1	1	Rear bumper assy	\$	39.60 <i>ali</i> ✓
2	2	Rear bumper bracket	\$	37.40 <i>de</i> ✓
3	2	Rear bumper side retainer	\$	189.60 <i>cu</i> 68 ✓
4	2	Rear bumper reflector	\$	683.40 <i>bt</i> ✓
5	1	Rear bootlid assy	\$	36.30 <i>x</i> nn
6	2	Rear bootlid rubber stopper	\$	125.70 <i>x</i> nn
7	2	Rear bootlid hinges	\$	167.90 <i>cu</i> ✓
8	1	Rear bootlid weatherstrip	\$	105.40 <i>bt</i> ✓
9	1	Rear bootlid lock mechanism	\$	67.40 <i>x</i> nn
10	1	Rear bootlid lock catch	\$	68.30 <i>ali</i> ✓
11	1	Rear bootlid centre logo	\$	56.80 <i>nn</i> ✓
12	1	Rear bootlid city emblem	\$	48.30 <i>nn</i> ✓
13	1	Rear bootlid IVTEC emblem	\$	176.20 <i>x</i> nn
14	1	Rear bootlid outer chrome garnish	\$	172.60 <i>x</i> nn
15	1	Rear bootlid inner board	\$	212.80 <i>cut</i> ✓
16	1	Rear left bootlid taillamp	\$	212.80 <i>cut</i> ✓
17	1	Rear right bootlid taillamp	\$	446.20 <i>cu</i> ✓
18	1	Rear left taillamp	\$	446.20 <i>cu</i> ✓
19	1	Rear right taillamp	\$	480.60 <i>bt</i> ✓
20	1	Rear end lower panel	\$	88.10 <i>de</i> ✓
21	1	Rear end lower panel top garnish	\$	88.00 <i>x</i> nn
22	2	Rear no plate lamp	\$	880.90 <i>bul</i> 560 ✓
23	1	Rear floor panel	\$	168.50 <i>cu</i> ✓
24	1	Rear spare tyre top board	\$	951.50 <i>x</i> R
25	1	Rear exhaust muffler assy	\$	36.30 <i>x</i> nn
26	2	Rear exhaust muffler rubber mounting	\$	6,576.50 4354.30
Less 20%			\$	1,315.30 -20%
			\$	5,261.20 3483.44

Special Nett Items

1	10	Rear bumper clips	\$	50.00 <i>3one</i>
2	8	Rear bootlid inner board clips	\$	30.00 <i>x</i> nn
3	4	Rear bootlid outer chrome garnish clips	\$	30.00 <i>x</i> nn
4	4	Rear end lower panel top garnish clips	\$	30.00 <i>2one</i>
5	1	Rear end lower panel sealant	\$	120.00 <i>404</i>
6	1	Rear floor panel sealant	\$	120.00 <i>x</i> nn
7	1	Rear floor panel insulator pad	\$	150.00 <i>100</i>
8	4	Rear bumper reverse sensor	\$	600.00 <i>200</i>
9	1	Rear view camera	\$	450.00 <i>x</i> nn
10	1	Rear no plate with garnish	\$	100.00 <i>x</i> nn
			\$	1,680.00 390

Total parts

\$ 6,941.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

No	Qty	Parts Description	Estimated Parts Price	
1	1	Front bumper assy	\$ 589.90	de ✓
2	1	Front bumper left bracket	\$ 66.30	de ✓
3	1	Front bumper right bracket	\$ 66.30	x nn
4	1	Front bumper left side retainer	\$ 63.20	de ✓
5	1	Front bumper right side retainer	\$ 63.20	x nn
6	1	Front grille assy	\$ 296.80	ann 186 ✓
7	1	Front grille emblem	\$ 68.60	nn ✓
8	1	Fron bumper lower grille assy	\$ 193.50	x nn
9	1	Front bonnet assy	\$ 792.40	x nn
10	1	Front bonnet insulator	\$ 128.20	x nn
11	1	Front right headlamp	\$ 428.30	ann ✓
12	1	Front left headlamp	\$ 428.30	ann ✓
13	1	Front right headlamp bracket	\$ 68.00	x nn
14	1	Front left headlamp bracket	\$ 68.00	x nn
15	1	Front support panel assy	\$ 492.80	x R
16	1	Front support panel top garnish	\$ 179.10	x nn
17	1	Front bonnet lock mechanism	\$ 155.70	x nn
18	1	Front bumper tow cover	\$ 68.80	x nn
19	1	Front bumper reinforcement	\$ 311.50	x nn
20	1	Front left fog lamp	\$ 252.10	ann ✓
21	1	Front right fog lamp	\$ 252.10	x nn
22	1	Front left fog lamp cover	\$ 68.50	x nn
23	1	Front right fog lamp cover	\$ 68.50	x nn
			\$ 5,170.10	2082.70
Less 20%			\$ 1,034.02	-20%
			<u>\$ 4,136.08</u>	1666.16

Special Nett Items

1	10	Front bumper clips	\$ 50.00	30 rec
2	4	Front grille clips	\$ 20.00	10 rec
3	1	Front no plate with garnish	\$ 100.00	x nn
4	1 set	Front bumper lower grille clips	\$ 40.00	x nn
5	6	Front support panel top garnish clips	\$ 30.00	x nn
6	1 set	Front bonnet insulator clips	\$ 40.00	x nn
			<u>\$ 280.00</u>	40

Total parts

\$ 4,416.08

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLM520E Honda City

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,000.00 400 300
2	To putty and spray painting front portion.	\$ 1,000.00 400 300
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To apply anti rust proofing to front affected area.	\$ 140.00 X
6	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 600
7	To putty and spray painting rear portion.	\$ 1,400.00 900
8	To check rear lighting and wiring.	\$ 50.00 30
9	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
10	To remove and install rear exhaust muffler assy.	\$ 120.00 60
11	To repair straighten and align both rear fenders.	\$ 350.00 X
12	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 60
13	To apply anti rust proofing to rear affected area.	\$ 140.00 40
14	To remove and install rear view camera.	\$ 80.00 30
15	To remove and install rear bumper reverse sensor.	\$ 80.00 30
16	To conduct chassis alignment.	\$ 350.00 X
17	Towing service.	\$ 100.00 X
Total labour :		\$ 6,560.00 2840

Total parts : \$ 11,357.28 8419.60

Total labour : \$ 6,560.00

Total repair cost : \$ 17,917.28 L/S - 6735.68 = 6750

Tanpin 9749549
 WP 28/4/22 2320pm.
 1/2 Resurvey after repair
 tanpin @ lkkauto.com
 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____