LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22003963/KQY3E2

20/06/2022 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001802960

Claimant Vehicle SLS1627T Insured Vehicle No: SJC6020T No:

Date of Loss: 23/04/2022 Nature of Claim: TP Claim No: 273389

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS1627T**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) 2ZR8125208 Engine No: Reg. Date: Chassis No: 11/09/2017 (Man. Year: 2017) ZYX102046049 Colour: Metallic Pearl White Odometer: 381648 km

Engine Capacity: 1797 cc Market Value/New Car Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

215/60 R17 Front Tyre Size: 215/60 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Triangle 6 mm Yokohama 2 mm Front Right Side: Triangle 6 mm Rear Right Side: Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,175.10	1,583.82	1,591.28	50.12
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,240.00	825.00	415.00	33.47
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,415.10	2,408.82	2,006.28	45.44
	Approved Total (Overridden) (S\$)		1,900.00		
	Nett Amount (S\$)	4,415.10	1,900.00	2,515.10	56.97

INSPECTION

Date of Assignment: 28/04/2022

Lian Her Motors (Ang Mo Kio) Date Inspected: 11/05/2022 Inspected At:

Blk 5038, Ang Mo Kio Industrial Park 2, #01-405

Singapore 569541

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jun 2022)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS1627T) Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	855.60 FL	*850.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*382.00 FL
3	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	251.20 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Serviceable	191.40 FL	*- FL
5	1		*REAR LOWER BUMPER	Dented / Cut	487.20 FL	*398.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
7	1		*REAR BOOT RUBBER	Serviceable	205.10 FL	*- FL
8	1		*REAR END PANEL	Repair	725.70 FL	*- FL
9	1		*REAR END PANEL INNER GARNISH	Serviceable	402.10 FL	*- FL
10	1		*REAR ANTENNA	Dented	175.10 FL	*175.10 FL
11	15		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
12	1		*REAR REVERSE SENSOR	Scratched / Shorted	200.00 FS	*200.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,156.80	2,035.10
			- List Item Discount	on L Items 25.00/25.00% (S\$)	981.70	451.28
				Total Parts (S\$)	3,175.10	1,583.82
				-		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	600.00	360.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	600.00	450.00
3	CHECK AND RECONNECT WIRING	New	40.00	15.00
	Gross Labour Cost (S\$)		1,240.00	825.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >