

**Note: This document has not been finalised.**

## **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|  |   |
|--|---|
| To: MSIG Insurance (Singapore) Pte. Ltd.<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807 | From: LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
|--|---|

Attn: Douglas Ong Chu Chong

Date: 08 Jun 2022

### **Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured            | : SJC6020T  |                         |              |
| Vehicle No         |   |                         |              |
| TP Vehicle No      | : SLS1627T  | Accident Date           | : 23/04/2022 |
| Make               | : TOYOTA C-HR HYBRID  | Assignment Date         | : 28/04/2022 |
| Date of Inspection | : 11/05/2022  | Est. Duration of Repair | : 2          |
| Inspection At      | : LIAN HER MOTORS (ANG MO KIO)<br>BLK 5038, ANG MO KIO INDUSTRIAL PARK 2, #01-405<br>SINGAPORE 569541 |                         |              |

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,415.10 |
| Revised Amount              | :S\$ | 2,408.83 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,408.83 |

|                 |      |          |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 1,900.00 |
|-----------------|------|----------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

( ) The vehicle is economical for repair

( ) The vehicle is not economical for repair

( ) Part-by-Part repair

( X ) Lump Sum repair

( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items)  
stated are subject to consistency check, part prices and labour cost.