



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0328/2022/JT  
**DATE** : 23-Apr-22  
**WIP** : 21101

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR NG PUI YEE (WU PEIYI)  
**ADDRESS** : 103 WEST COAST VALE  
#35-12  
SINGAPORE 126754  
**TELEPHONE** : HP +65 91836960  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210000336  
**VEHICLE NO** : **SMX 4622 Z**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S TRONIC  
**MODEL YEAR** : 13/1/2021  
**ENGINE NO** : CZD C22958  
**CHASSIS NO** : WAUZZZF38M1055491  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 21-Apr-22  
**PLACE OF ACCIDENT** : JURONG TOWN HALL ROAD  
& BOON LAY WAY



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4622 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHT'S, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND FRONT CAMERA ASSY.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ <del>400.00</del>	250
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM.	S/N \$ 1,700.00	x.
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	x.
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>4,800.00</del>	500
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ <del>2,700.00</del>	550
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>11,472.00</u></b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z**

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>Distorted</i>	1	\$	1,235.00	✓	
2	FRONT BUMPER CLOSING ELEMENT - RH <i>Delud</i>	1	\$	66.00	✓	
3	FRONT BUMPER GRILLE - CENTER <i>Delud</i>	1	\$	242.00	✓	
4	FRONT BUMPER GRILLE - RH <i>Missing</i>	1	\$	124.00	✓	
5	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$	212.00	?	
6	FRONT BUMPER SPOILER <i>Delud</i>	1	\$	426.00	✓	
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	1	\$	171.00	✓	
8	RADIATOR GRILLE <i>crushed</i>	1	\$	1,594.00	✓	
9	RADIATOR GRILLE STRIKER PLATE <i>?</i>	1	\$	271.00	?	
10	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	114.00	?	
11	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	974.00	?	
12	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$	43.00	?	
13	FRONT FENDER - RH <i>NEW</i>	1	\$	1,445.00	+	
14	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$	66.00	+	
15	FRONT FENDER BRACE - RH <i>new</i>	1	\$	98.00	+	
16	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$	260.00	+	
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$	105.00	+	
18	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$	566.00	✓	
19	HEADLIGHT - RH <i>let</i>	1	\$	5,952.00	✓	
20	HEADLIGHT POWER MODULE <i>NEW</i>	1	\$	850.00	+	
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$</b>	<b>14,814.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	LED HEAT SINK	1	\$	870.00	X
22	HEADLIGHT MOUNTING - RH	1	\$	132.00	+
23	LIFT CYLINDER - RH	1	\$	231.00	+
24	FRONT PARKING AID SENSOR	2	\$	530.00	+
25	HORN - RH	1	\$	145.00	+
26	HORN SUPPORT - RH	1	\$	25.00	+
27	LOCK CARRIER	1	\$	1,412.00	+
28	RADIATOR AIR GUIDE - RH	1	\$	43.00	?
29	RADIATOR COOLANT	4	\$	188.00	+
30	FRONT NO PLATE	S/N	\$	60.00	—
31	SUNDRIES		\$	400.00	?
<b>TOTAL SPARE PARTS</b>		:	\$	<b>18,850.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>11,472.00</b>	
<b>GRAND TOTAL</b>		:	\$	<b>30,322.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*  
SURVEYED DATE : *27/03/22*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT