



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0328/2022/JT
DATE : 23-Apr-22
WIP : 21101

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,
3 days - ok - Jy - 5 Jul 22

OWNER'S NAME : MR NG PUI YEE (WU PEIYI)
ADDRESS : 103 WEST COAST VALE
#35-12
SINGAPORE 126754
TELEPHONE : HP +65 91836960
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210000336
VEHICLE NO : **SMX 4622 Z**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 13/01/2021
ENGINE NO : CZD C22958
CHASSIS NO : WAUZZZF38M1055491
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-22
PLACE OF ACCIDENT : JURONG TOWN HALL ROAD
& BOON LAY WAY

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4622 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHT'S, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND FRONT CAMERA ASSY.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	\$ 250.00
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM.	S/N \$ 1,700.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	\$ 500.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 2,700.00	\$ 550.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 11,472.00	\$ 1,972.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,235.00	\$ 987.60
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00	\$ 52.32
3	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	\$ 193.60
4	FRONT BUMPER GRILLE - RH	1	\$ 124.00	\$ 98.80
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
6	FRONT BUMPER SPOILER	1	\$ 426.00	\$ 340.80
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	\$ 136.40
8	RADIATOR GRILLE	1	\$ 1,594.00	\$ 1,275.20
9	RADIATOR GRILLE STRIKER PLATE	1	\$ 271.00	\$ 216.80
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00	
11	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	\$ 778.80
12	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	
13	FRONT FENDER - RH	1	\$ 1,445.00	
14	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
15	FRONT FENDER BRACE - RH	1	\$ 98.00	
16	FRONT WHEEL HOUSING LINER- RH	1	\$ 260.00	
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
18	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$ 452.00
19	HEADLIGHT - RH	1	\$ 5,952.00	\$ 4,761.60
20	HEADLIGHT POWER MODULE	1	\$ 850.00	
SUB TOTAL SPARE PARTS			\$ 14,814.00	\$ 9,293.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>C/F</i>		\$ 9,293.92
21	LED HEAT SINK	1	\$ 870.00	
22	HEADLIGHT MOUNTING - RH	1	\$ 132.00	\$ 105.20
23	LIFT CYLINDER - RH	1	\$ 231.00	
24	FRONT PARKING AID SENSOR	2	\$ 530.00	
25	HORN - RH	1	\$ 145.00	
26	HORN SUPPORT - RH	1	\$ 25.00	
27	LOCK CARRIER	1	\$ 1,412.00	
28	RADIATOR AIR GUIDE - RH	1	\$ 43.00	\$ 34.08
29	RADIATOR COOLANT	4	\$ 188.00	
30	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
31	SUPPLEMENTARY		\$ 612.00	\$ 166.48
32	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 19,462.00	\$ 9,659.68
TOTAL LABOUR CHARGES		:	\$ 11,472.00	\$ 1,972.00
GRAND TOTAL		:	\$ 30,934.00	\$ 11,631.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-30/06/22



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd	Estimate No.	PA/OD/0328/2022/JT
78 Shenton Way	Date	01-Jun-22
#07-16 AIG Building	Service Advisor	CHANG
Singapore 079120	Pages	1 of 1
Attn: Mr. Adrian Ling - Motor Claims Dept	Regn No	SMX 4622 Z
Tel: 6841 0055 / Fax: 6256 4315	Model No	AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT BUMPER TOP COVER	\$ 137.00	\$ 109.60
2	STICKER FOR AIR CONDITIONER	\$ 9.00	\$ 6.64
3	SIGN ' CAUTION ' STICKER	\$ 16.00	\$ 12.40
4	RADIATOR AIR GUIDE - LOWER	\$ 48.00	\$ 37.84
5	REFRIGERANT LINE (A/C COMPRESSOR -> A/C CENDENSER)	\$ 402.00	
GRAND TOTAL		\$ 612.00	\$ 166.48

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT