

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0328/2022/JT
DATE : 23-Apr-22
WIP : 21101

Hui Rong
\$11631.68

03 Days.
H.S.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NG PUI YEE (WU PEIYI)
ADDRESS : 103 WEST COAST VALE
#35-12
SINGAPORE 126754
TELEPHONE : HP +65 91836960
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210000336
VEHICLE NO : **SMX 4622 Z**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 13/1/2021
ENGINE NO : CZD C22958
CHASSIS NO : WAUZZZF38M1055491
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Apr-22
PLACE OF ACCIDENT : JURONG TOWN HALL ROAD
& BOON LAY WAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4622 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHT'S, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND FRONT CAMERA ASSY.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM.	S/N \$ 1,700.00	x.
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	x.
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	500
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 2,700.00	550
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,472.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	S	1,235.00	✓ 987.6
2	FRONT BUMPER CLOSING ELEMENT - RH <i>Delnd</i>	1	S	66.00	✓ 52.32
3	FRONT BUMPER GRILLE - CENTER <i>Delnd</i>	1	S	242.00	✓ 193.6
4	FRONT BUMPER GRILLE - RH <i>Missing</i>	1	S	124.00	✓ 98.8
5	FRONT BUMPER CLOSING ELEMENT <i>Not nee</i>	1	S	212.00	X
6	FRONT BUMPER SPOILER <i>Delnd</i>	1	S	426.00	✓ 340.8
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	1	S	171.00	✓ 136.4
8	RADIATOR GRILLE <i>Cracked</i>	1	S	1,594.00	✓ 1275.2
9	RADIATOR GRILLE STRIKER PLATE <i>Cracked</i>	1	S	271.00	✓ 216.8
10	FRONT BUMPER FOAM FILLER PIECE <i>Not nee</i>	1	S	114.00	X
11	FRONT BUMPER REINFORCEMENT BEAM <i>Broken.</i>	1	S	974.00	✓ 778.8
12	FRONT BUMPER GUIDE SECTION - RH <i>Not nee</i>	1	S	43.00	X
13	FRONT FENDER - RH <i>Not nee</i>	1	S	1,445.00	X
14	FRONT FENDER ATTACHMENT PARTS <i>Not nee</i>	1	S	66.00	X
15	FRONT FENDER BRACE - RH <i>Not nee</i>	1	S	98.00	X
16	FRONT WHEEL HOUSING LINER - RH <i>Not nee</i>	1	S	260.00	X
17	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not nee</i>	1	S	105.00	X
18	FRONT WHEEL ARCH COVER - LH / RH <i>Not nee</i>	2	S	566.00	✓ 452
19	HEADLIGHT - RH <i>Lit</i>	1	S	5,952.00	✓ 4761.6
20	HEADLIGHT POWER MODULE <i>Not nee</i>	1	S	850.00	X
SUB TOTAL SPARE PARTS			:	\$ 14,814.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4622 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	LED HEAT SINK <i>Not new</i>	1	\$	870.00 <i>+</i>	
22	HEADLIGHT MOUNTING - RH <i>cracked</i>	1	\$	132.00 <i>+</i>	105.2
23	LIFT CYLINDER - RH <i>Not new</i>	1	\$	231.00 <i>+</i>	
24	FRONT PARKING AID SENSOR <i>new</i>	2	\$	530.00 <i>+</i>	
25	HORN - RH <i>new</i>	1	\$	145.00 <i>+</i>	
26	HORN SUPPORT - RH <i>new</i>	1	\$	25.00 <i>+</i>	
27	LOCK CARRIER <i>new</i>	1	\$	1,412.00 <i>+</i>	
28	RADIATOR AIR GUIDE - RH <i>cracked</i>	1	\$	43.00 <i>+</i>	34.08
29	RADIATOR COOLANT <i>new</i>	4	\$	188.00 <i>+</i>	
30	FRONT NO PLATE <i>new</i>	S/N	\$	60.00 <i>-</i>	60
31	SUNDRIES <i>Not new</i>		\$	400.00 <i>+</i>	
TOTAL SPARE PARTS		:	\$	18,850.00	
TOTAL LABOUR CHARGES		:	\$	11,472.00	
GRAND TOTAL		:	\$	30,322.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

❖ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 27/03/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not authorised, 03 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ALLAN WU
CLAIMS CONSULTANT

Acknowledged by Repairer
Signature:
Date: