

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE: 6/6/2022

M/S India International Insurance Pte Ltd

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GBB2248E NISSAN CABSTAR

		NETT ITEMS	
01)	1 PC TAILGATE	\$ 1,459.60	X
02)	1 PC TAILGATE NISSAN STICKER	\$ 80.10	✓
03)	1 PC TAILLAMP	\$ 350.40	✓
04)	1 PC RH RUBBER STOPPER	\$ 30.00	X
05)	1 PC TAILGATE LOCK	\$ 80.20	X
06)	1 PC CABSTAR EMBLEM	\$ 79.50	✓
07)	1 PC FRONT PANEL	\$ 1,708.70	✓
08)	1 PC FRONT BUMPER WITH REINFORCEMENT	\$ 1,031.00	✓
		\$ 4,819.50	
	LESS 10%	-481.95	
		\$ 4,337.55	
09)	1 PC TIPPER LOWER MEMBER	\$ 550.00	✓
10)	1 PC NUMBER PLATE	\$ 30.00	20
11)	1 SET SEALANT	\$ 50.00	X
12)	1 SET REVERSE SENSOR	\$ 280.00	200
13)	1 PC 70 KM	\$ 15.00	✓
14)	1 PC 13 PAX	\$ 15.00	✓
15)	REMOVE & REFIX FRONT WINDSCREEN	\$ 120.00	60
16)	SPRAY PAINTING (WIPER PANEL ,FRONT PANEL, FRONT BUMPER	\$ 660.00	500
17)	LABOUR CHARGE (FRONT)	\$ 600.00	580
18)	SPRAY PAINTING (TAILGATE, LOWER MEMBER)	\$ 440.00	400
19)	LABOUR CHARGE (REAR)	\$ 500.00	450
20)	WIRING CHECK	\$ 30.00	20
21)	TUFFCOAT	\$ 80.00	50
		\$ 7,707.55	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2
Acknowledged by Repairer
Signature:

Not Adhered
her
n/s \$4300
6 days
7/6/22
Jin Auto Services Pte Ltd

228488
102
256392
710
2060
539392