

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 26/04/2022

Estimated repair cost for vehicle no: YQ6197R TOYOTA DYNA 150 6AT

CHASSIS: JHHAGV4680K001703 (2021)

27/04/2022

TP AL.
Xiao Chen.

S/N	Qty	Items	U/price	Amount
1	1	REAR TAILGATE <i>Dented.</i>	\$1,314.90	\$1,314.90 ✓
2	1	REAR TAILGATE LOCK RH <i>Dented</i>	\$230.70	\$230.70 ✓
3	1	REAR TAILGATE EMBLEM STICKER TOYOTA <i>new</i>	\$301.20	\$301.20 ✓
4	1	REAR TAILGATE EMBELM STICKER DYNA <i>new</i>	\$61.90	\$61.90 ✓
5	1	REAR TAILLAMP RH <i>Cracked</i>	\$378.90	\$378.90 ✓
6	1	REAR TAILLAMP BRACKET RH <i>Best.</i>	\$270.10	\$270.10 ✓
7	1	REAR TAILGATE RUBBER STOPPER RH <i>at</i>	\$61.30	\$61.30 ✓
8		REAR REFLECTOR ROUND <i>cracked</i>	<i>28.90</i>	<i>28.90</i> ✓
9	1	REAR EXHUAUST MUFFLER <i>New one</i>	<i>980.50</i>	<i>980.50</i> ✓
10	1	REAR NUMBER PLATE BRACKET <i>Best</i>	<i>158.40</i>	<i>158.40</i> ✓

2806.30

2104.72

TOTAL : \$2,619.00
LESS 25 % \$654.75
SUB-TOTAL : \$1,964.25

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR SAFETY BAR <i>Dented.</i>	\$850.00	\$850.00 ✓ <i>800.</i>
2	2	REAR SAFETY BAR BRACKET <i>Best</i>	\$140.00	\$280.00 ✓ <i>200.</i>
3	1	REAR SAFETY BAR STICKER <i>New</i>	\$120.00	\$120.00 ✓ <i>80</i>
4	1	REAR REVERSE SENSOR <i>Damaged</i>	\$280.00	\$280.00 ✓ <i>200</i>

1280

TOTAL: \$1,530.00

TOTAL PARTS \$3,494.25

YQ6197R TOYOTA DYNA

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME
- 6 LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER , TO REPAIR & STRAIGHTEN REAR EXHUAUST PIPE

1860 700.
\$1,200.00
~~\$800.00~~ 700
~~\$80.00~~ 30
~~\$300.00~~ 80
~~\$500.00~~ + 20
250.
~~\$300.00~~ +

Subtotal :- \$3,180.00

Total:- \$6,674.25

Admin C;
L/s 28/04/22 .
04 Days.

Total: \$224.72
L/s: 4.2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4.2K