



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2208025
3 ANSON ROAD #16-00	INV Date	29/12/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22003990/Upa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	GBE 8426C
Insured Veh.	SMW 1980P
Claim No.	SNM22D202957/C02
Policy No.	DMPCSNW00174852100
Accident Date	27/04/2022
Inspection Date	28/04/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22003990/Upa3q2 Date: 29/12/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMW 1980P	Veh. Inspected	GBE 8426C
Policy No.	DMPCSNW00174852100	Coverage (\$)	0.00
Claim No.	SNM22D202957/C02	Excess (\$)	0.00
Assign From		Assign Date	28/04/2022
2. Vehicle Particulars & Condition			
Make & Model	KIA K2500 (M)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNCSJX76LG7037507	Colour	WHITE
Odometer	210780 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	KAPSEN	6 mm
L/H Front Tyre	195 R15	KAPSEN	6 mm
R/H Rear Tyre	155 R12 (D)	KAPSEN	6/6 mm
L/H Rear Tyre	155 R12 (D)	KAPSEN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/04/2022	Inspection Date	28/04/2022
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 8426C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	DENTED / BENT	1,500.00	1,150.00
1	SET TAILGATE 'KIA MOTORS' STICKER	NECESSARY	250.00	110.00
1	TAILGATE LOWER MEMBER	BENT	680.00	600.00
2	TAILLAMPS @\$245.00	CRACKED	490.00	392.00
2	TAILLAMP PANELS @\$450.00	BENT / TWISTED	900.00	700.00
1	TAILLAMP PANEL STOPPER O/S	TORN	60.00	20.00
1	REAR SPARE TYRE CHAIN & HOLDER	BENT / JAMMED	388.00	305.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	464.00	-
1	REAR CROSS MEMBER STEP BRACKET	BENT/ CRACKED	485.00	485.00
1	REAR STEP 'U' BRACKET	BENT	190.00	190.00
1	REAR LICENCE PLATE PANEL	BENT	108.00	108.00
	LESS 10% DISCOUNT		-	-406.00
			5,515.00	3,654.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	SET REAR REVERSE SENSOR (SN)	CRACKED	280.00	200.00
1	SET REAR REVERSE CAMERA (SN)	DAMAGED / BROKEN	380.00	300.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR REVERSE LAMP (SN)	BROKEN	52.00	52.00
1	REAR REVERSE LAMP BULB (SN)	CRACKED	10.00	5.00
			792.00	607.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO RESET & DISGNOSTIC SYSTEM.		120.00	50.00
	TO DISMANTLE & REFIX REAR CARGO DECK PANEL .	NOT NECESSARY	500.00	-
	TO SPRAY RUST PROOFING.		100.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST .		900.00	600.00

Report Ref No. CC6/CTI22003990/Upa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,200.00	600.00
			2,950.00	1,370.00
	<b>GRAND TOTAL</b>		<b>9,257.00</b>	<b>5,631.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,500.00</b>

Report Ref No. CC6/CTI22003990/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBE 8426C

## INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBE 8426C

## RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 8426C

RE-INSPECTION

