

Likie Hsc4070y

Not Authorized  
see

28/4/22

2/3 = 4500 /  
4 days.

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

VEHICLE No: GBE 8426C

1PC	TAILGATE	20/benf	1150.00	\$1,500.00
1SET	TAILGATE ' KIA MOTORS' STICKER	ben	110.00	\$250.00
1PC	TAILGATE LOWER MEMBER	benf	600.00	\$680.00
2PCS	TAILLAMPS @\$245.00	one	196 x 2 = 392	\$490.00
2PCS	TAILLAMP PANELS @\$450.00	benf/ben	350 x 2 = 700	\$900.00
1PC	TAILLAMP PANEL STOPER O/S	ben	20	\$60.00
1PC	REAR SPARE TYRE CHAIN & HOLDER	benf/ben	305	\$388.00
1PC	REAR EXHAUST	ben		\$464.00
1PC	REAR CROSS MEMBER STEP BRACKET	benf/ben		\$485.00
1PC	REAR STEP 'U' BRACKET	benf		\$190.00
1PC	REAR LICENCE PLATE PANEL	benf	110%	\$108.00
				\$5,515.00

S.NETT

1PC	REAR LICENCE PLATE	benf	\$50.00	40
1SET	REAR REVERSE SENSOR	one	\$280.00	200
1SET	REAR REVERSE CAMERA	one/ben	\$380.00	300
1PC	REAR 70 km/h STICKER	ben	\$20.00	10
1PC	REAR REVERSE LAMP	ben	\$52.00	✓
1PC	REAR REVERSE LAMP BULB	one	\$10.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	50
TO RESET & DISGNOSTIC SYSTEM	\$120.00	50
TO DISMANTLE & REFIX REAR CARGO DECK PANEL	\$500.00	X
TO SPRAY RUST PROOFING	\$100.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$900.00	600
TO PUTTY & SPRAY PAINTING	\$1,200.00	600
<b>TOTAL</b>	<b>\$9,257.00</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party-survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-4060  
10%  
P-3654  
S-N-607  
L-1370  
5631  
292  
4504.