



A S AUTO SERVICE

No 1, Kaki Bukit Ave 6
#01-106/108 Autobay @ Kaki Bukit
Singapore 417800
Tel: 6744 8183
Co. Reg No: 53073291B

To Allianz Insurance Singapore Pte. Ltd.

Vehicle Number: SMW 5908Z

Date of Accident: 21/04/2022

Policy Number: SP2001284953

PARTS REPLACEMENT - LIST ITEMS	Qty	Unit Price	List Price \$	
LH Front Fender <i>one</i>	1	4,350.00	4,350.00	✓
RH Front Fender <i>Debris</i>	1	4,350.00	4,350.00	✓
RH Front Fender Crowning <i>torn</i>	1	230.00	230.00	✓
RH Front Fender Bracket <i>Debris</i>	1	800.00	800.00	✓
Front Bonnet <i>Debris</i>	1	13,505.00	13,505.00	✓
Front Bonnet Sponge <i>dislodged</i>	1	250.00	250.00	✓
Front RH Headlamp <i>dislodged</i>	1	3,900.00	3,900.00	✓
Front RH Headlamp Bracket <i>Debris</i>	1	190.00	190.00	✓
Left LH Headlamp ?	1	3,900.00	3,900.00	?
Front Bumper <i>torn</i>	1	4,850.00	4,850.00	✓
Front Bumper Nozzle ?	2	180.00	360.00	?
Front Bumper Nozzle Hose Assembly Set ?	1	250.00	250.00	?
Front Bumper Fog Lamp <i>o/s dislodged</i> <i>4/5 m</i>	2	175.00	350.00	✓
Front Bumper Sensor <i>dislodged / Dam</i>	4	150.00	600.00	✓
Front Bumper Sensor Wire Set ?	1	580.00	580.00	?
Front Bumper Lower Cover <i>broken</i>	1	280.00	280.00	✓
Front Reinforcement ?	1	2,750.00	2,750.00	?
Side Skirt <i>4/5 m</i> <i>o/s missing</i> <i>broken</i>	2	1,200.00	2,400.00	✓
Front Bumper Grille <i>broken</i>	1	1800.00	1800.00	✓
Front Bumper Grill Inner Air Converter <i>torn</i>	1	390.00	390.00	✓
Left Side Mirror Assembly <i>broken</i>	1	1800.00	1800.00	✓
RH Door Air Bag <i>actived</i>	1	1,110.00	1,110.00	✓
Air Bag Inscription Plate <i>dislodged</i>	1	135.00	135.00	✓
RH Seat Side Air Bag <i>actived</i>	1	1,200.00	1,200.00	✓
Seat Cover Set <i>torn</i>	1	2,700.00	2,700.00	✓
Front Cross Member Frame <i>rip</i>	1	4,850.00	4,850.00	X
<i>RH</i> Front Shock Absorber ?	1	2,100.00	2,100.00	?
<i>RH</i> Front Top Arm ?	1	980.00	980.00	?
<i>RH</i> Front Lower Arm ?	1	1,400.00	1,400.00	?
<i>RH</i> Front Knuckle Arm ?	1	1,300.00	1,300.00	?
<i>RH</i> Front Steering Rack ?	1	4,980.00	4,980.00	?
<i>RH</i> Front Steering Rack Cooler <i>4/5 m</i> <i>(punctured)</i>	1	300.00	300.00	✓
Right Front Tyre Rim <i>cut</i>	1	2,300.00	2,300.00	✓



A S AUTO SERVICE

No 1, Kaki Bukit Ave 6
#01-106/108 Autobay @ Kaki Bukit
Singapore 417800
Tel: 6744 8183
Co. Reg No: 53073291B

Right Rear Top Arm ?	1	850.00	850.00	?
Right Rear Lower Arm ?	1	1,400.00	1,400.00	?
Right Rear Tie Rod NS	1	240.00	240.00	X
Right Rear Knuckle Arm ?	1	1,350.00	1,350.00	?
Right Rear Shock Absorber ?	1	1,970.00	1,970.00	?
Radiator (coolant) broken 1 set	1	1,350.00	1,350.00	✓
Radiator Fan Assembly ?	1	1,100.00	1,100.00	?
Radiator Air Duct ?	1	293.00	293.00	?
Aircon Condenser 1 set / punctured	1	1,230.00	1,230.00	✓
Engine Compartment Top Cover broken	1	400.00	400.00	✓
Rear Tyre Rim cut	1	2,300.00	2,300.00	✓
Sub Total			83,718.00	
LABOUR & MISC. CHARGES				
Spray Painting			3,800.00	1200/-
Panel Beating 1 air bag removed by right etc			4,500.00	1600/-
Removal and installation of radiator and condenser and aircon gas			500.00	150/-
Removal and installation front and rear under carriage for damaged part			3800.00	500/-
Sub Total			12,600.00	
Grand Total			96,318.00	

29/04/222 C 1000w

Not Antenna

Ryan 13 days.

2 KK Auto

Pending Part prices
check

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: