



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0341/2022/JT
DATE : 26-Apr-22
WIP : 21563

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAN YI TING
ADDRESS : BLK 130 BEDOK RESERVOIR ROAD
#10-1353
SINGAPORE 470130
TELEPHONE : HP +65 91709070
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700094139-04
VEHICLE NO : SLV 4371 U
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 28/12/2017
ENGINE NO : CVN 045312
CHASSIS NO : WAUZZZF41JA023310
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Apr-22
PLACE OF ACCIDENT : GRANDSTAND CAR PARK ZONE B


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4371 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	* ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	750
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	? ✗
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 2 x 500
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1650 Bumper - 1 2 x 550
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,502.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>BR</i>	1	TBC	1688.80 ✓
2	FRONT BUMPER FIXING PARTS <i>X NN</i>	1	TBC	
3	FRONT BUMPER SECURING STRIP <i>(RH) - BT</i>	<i>21</i>	\$	79.00 31.60 ✓
4	FRONT BUMPER GRILLE - CENTER <i>X NN</i>	1	\$	219.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$ <i>BR</i>	254.00 ✓ 203.20
6	FRONT BUMPER AIR GUIDE - RH <i>? X NN</i>	1	\$	72.00
7	RADIATOR GRILLE <i>X NN</i>	1	\$	1,277.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>? X NN</i>	1	\$	151.00
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ <i>BR</i>	139.00 ✓ 110.80
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ <i>DD</i>	899.00 ✓ 719.20
11	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$ <i>BR</i>	41.00 ✓ 32.24
12	FRONT BUMPER BRACKET - RH <i>? X NN</i>	1	\$	254.00
13	FRONT BUMPER TOP COVER <i>BR</i>	1	\$	143.00 ✓ 114
14	CAUTION STICKER <i>AK</i>	1	\$	16.00 ✓ 12.40
15	AIR COND STICKER <i>AK</i>	1	\$	9.00 ✓ 6.64
16	FRONT BUMPER LOCK CARRIER BRACKET <i>BR</i>	1	\$	154.00 ✓ 122.80
17	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ <i>NEC</i>	64.00 ✓ 51.04
18	POP RIVET <i>? X NN</i>	4	\$ <i>NEC</i>	4.00 ✓ 2.88
19	HORN - RH <i>? X NN</i>	1	\$	139.00
20	HORN SUPPORT - RH <i>? X NN</i>	1	\$	33.00
SUB TOTAL SPARE PARTS		:	\$	3,947.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
21	FRONT FENDER - RH / <i>DD</i>	1	\$	861.00 ✓	688.80
22	FRONT FENDER ATTACHMENT PARTS X NN	1	\$	211.00	
23	FRONT FENDER CLOSING ELEMENT - RH / <i>MC</i>	1	\$	81.00 ✓	64.24
24	FRONT FENDER BRACKET - RH / <i>MC</i>	1	\$	41.00 ✓	32.72
25	FRONT FENDER BRACE - RH ?	1	\$ DD	132.00 ✓	105.20
26	FRONT FENDER BRACKET CENTER - RH X NN	1	\$	55.00	
27	FRONT WHEEL HOUSING LINER - RH <i>MC</i> ?	1	\$ TN	262.00 ✓	209.60
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	X NN	TBC	
29	FRONT WHEEL SPOILER / <i>BR</i>	1	\$	82.00 ✓	65.12
30	FRONT WHEEL SPOILER LOWER - RH X NN	1	\$	40.00	
31	FRONT WHEEL SPOILER STONE CHIP GUARD - RH X NN	1	\$	57.00	
32	FRONT FENDER LEDGE COVER LONG - RH ? X NN	1	\$	35.00	
33	FRONT FENDER LEDGE COVER SHORT - RH / <i>BR</i>	1	\$	26.00 ✓	20.16
34	HEADLIGHT - RH / <i>BR</i>	1		TBC 6154.40 ✓	
35	HEADLIGHT POWER MODULE ?	1	\$ BR	840.00 ✓	672
36	HEADLIGHT CONTROL UNIT ? X NN	1	\$	840.00	
37	HEADLIGHT HOSE - RH ? X NN	1	\$	42.00	
38	SPACER ? X NN	3	\$	136.00	
39	LIFT CYLINDER - RH ?	1	\$ BR	231.00 ✓	184.40
40	LIFT CYLINDER BRACKET ?	1	\$ BR	7.00 ✓	5.44
SUB TOTAL SPARE PARTS		:	\$	3,979.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	LIFT CYLINDER CORRUGATED PIPE ?	1	\$ TN	107.00 ✓ 85.60
42	LIFT CYLINDER HOSE - INNER ? X NN	1	\$	45.00
43	LOCK CARRIER ? X NN	1	\$	1,127.00
44	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ NEC	21.00 ✓ 16.32
45	RADIATOR COOLANT ? X NN	6	\$	282.00
46	RADIATOR AIR GUIDE INNER - RH ? X NN	1	\$	32.00
47	RADIATOR AIR GUIDE OUTER - RH ? X NN	1	\$	14.00
48	RADIATOR AIR GUIDE UPPER ? X NN	1	\$	19.00
49	FRONT NO PLATE X NN	S/N	\$	120.00
50	SUNDRIES ?		\$ NEC	350.00 32.56 ✓
TOTAL SPARE PARTS		:	\$	10,043.00
TOTAL LABOUR CHARGES		:	\$	8,502.00
GRAND TOTAL		:	\$	18,545.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKR)
27/4/22, 3.07

00- M R
EXN S- ?
P/P
M B L y
5 dy

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4371 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	750
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,400.00	? X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1650
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,502.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>BR</i>	1	TBC	1688.80 ✓
2	FRONT BUMPER FIXING PARTS <i>X NN</i>	1	TBC	
3	FRONT BUMPER SECURING STRIP <i>(RH) - BT</i>	<i>21</i>	\$	79.00 31.60 ✓
4	FRONT BUMPER GRILLE - CENTER <i>X NN</i>	1	\$	219.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$ <i>BR</i>	254.00 ✓ 203.20
6	FRONT BUMPER AIR GUIDE - RH <i>?</i> <i>X NN</i>	1	\$	72.00
7	RADIATOR GRILLE <i>X NN</i>	1	\$	1,277.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>?</i> <i>X NN</i>	1	\$	151.00
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ <i>BR</i>	139.00 ✓ 110.80
10	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ <i>DD</i>	899.00 ✓ 719.20
11	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$ <i>BR</i>	41.00 ✓ 32.24
12	FRONT BUMPER BRACKET - RH <i>?</i> <i>X NN</i>	1	\$	254.00
13	FRONT BUMPER TOP COVER <i>BR</i>	1	\$	143.00 ✓ 114
14	CAUTION STICKER <i>AK</i>	1	\$	16.00 ✓ 12.40
15	AIR COND STICKER <i>AK</i>	1	\$	9.00 ✓ 6.64
16	FRONT BUMPER LOCK CARRIER BRACKET <i>BR</i>	1	\$	154.00 ✓ 122.80
17	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ <i>NEC</i>	64.00 ✓ 51.04
18	POP RIVET <i>?</i>	4	\$ <i>NEC</i>	4.00 ✓ 2.88
19	HORN - RH <i>?</i> <i>X NN</i>	1	\$	139.00
20	HORN SUPPORT - RH <i>?</i> <i>X NN</i>	1	\$	33.00
SUB TOTAL SPARE PARTS		:	\$	3,947.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT FENDER - RH / <i>DD</i>	1	\$	861.00 ✓ 688.80
22	FRONT FENDER ATTACHMENT PARTS X NN	1	\$	211.00
23	FRONT FENDER CLOSING ELEMENT - RH / <i>MC</i>	1	\$	81.00 ✓ 64.24
24	FRONT FENDER BRACKET - RH / <i>MC</i>	1	\$	41.00 ✓ 32.72
25	FRONT FENDER BRACE - RH ?	1	\$ DD	132.00 ✓ 105.20
26	FRONT FENDER BRACKET CENTER - RH X NN	1	\$	55.00
27	FRONT WHEEL HOUSING LINER - RH <i>MC</i> ?	1	\$ TN	262.00 ✓ 209.60
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	X NN	TBC
29	FRONT WHEEL SPOILER / <i>BR</i>	1	\$	82.00 ✓ 65.12
30	FRONT WHEEL SPOILER LOWER - RH X NN	1	\$	40.00
31	FRONT WHEEL SPOILER STONE CHIP GUARD - RH X NN	1	\$	57.00
32	FRONT FENDER LEDGE COVER LONG - RH ? X NN	1	\$	35.00
33	FRONT FENDER LEDGE COVER SHORT - RH / <i>BR</i>	1	\$	26.00 ✓ 20.16
34	HEADLIGHT - RH / <i>BR</i>	1	TBC	6154.40 ✓
35	HEADLIGHT POWER MODULE ?	1	\$ BR	840.00 ✓ 672
36	HEADLIGHT CONTROL UNIT ? X NN	1	\$	840.00
37	HEADLIGHT HOSE - RH ? X NN	1	\$	42.00
38	SPACER ? X NN	3	\$	136.00
39	LIFT CYLINDER - RH ?	1	\$ BR	231.00 ✓ 184.40
40	LIFT CYLINDER BRACKET ?	1	\$ BR	7.00 ✓ 5.44
SUB TOTAL SPARE PARTS		:	\$	3,979.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	LIFT CYLINDER CORRUGATED PIPE ?	1	\$ TN	107.00 ✓ 85.60
42	LIFT CYLINDER HOSE - INNER ? X NN	1	\$	45.00
43	LOCK CARRIER ? X NN	1	\$	1,127.00
44	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ NEC	21.00 ✓ 16.32
45	RADIATOR COOLANT ? X NN	6	\$	282.00
46	RADIATOR AIR GUIDE INNER - RH ? X NN	1	\$	32.00
47	RADIATOR AIR GUIDE OUTER - RH ? X NN	1	\$	14.00
48	RADIATOR AIR GUIDE UPPER ? X NN	1	\$	19.00
49	FRONT NO PLATE X NN	S/N	\$	120.00
50	SUNDRIES ?		\$ NEC	350.00 32.56 ✓
TOTAL SPARE PARTS		:	\$	10,043.00
TOTAL LABOUR CHARGES		:	\$	8,502.00
GRAND TOTAL		:	\$	18,545.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKR)
27/4/22, 3.07p

00- M R
EXN S- ?
P/P
M B L y
5 dy

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT