

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0152/22
DATE : 26-APR-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MDM ANG HAO @HONG HAO
ADDRESS : BLK 406B FERNVALE ROAD
#06-49
S(792406)
TELEPHONE NO : 8568 8652

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DMPCSNW22231892101
VEHICLE NO : SMF7919T
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12232415J
CHASSIS NO : JN1TAAE12Z0982396
MILEAGE : 79521 KM
DATE IN : 26/04/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 25/04/2022

not Authored
2000
excess 500
29/4/22
To be ph. before printing
7 days.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF7919T

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER.	1400.00	980
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1350.00	1000
3 ZZ/003	REMOVE AND INSTALL REAR W/SCREEN GLASS.	180.00	150
4 ZZ/004	REMOVE AND INSTALL TAIL GATE DOOR MECHANISM.	80.00	✓
5 ZZ/005	APPLY SEALANT TO TAIL GATE BACK DOOR.	100.00	✓
6 ZZ/006	PERFORM RUST PROOFING TO REAR PANEL.	120.00	✓
7 ZZ/007	REMOVE AND INSTALL REVERSE SENSOR - RENEW IF NEC RESET AND FUNCTION TEST.	55.00	✓
8 ZZ/008	RENEW REAR LICENCE PLATE.		
TOTAL LABOUR CHARGES		3285.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMP7919T

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
1	SUNDRIES	NFN			50.00 ?
2	REAR LICENCE PLATE	RLP		su	60.00 x
3	REAR COMB LAMP LH	26555-5WK0A	470.60 ?		
4	REAR COMB LAMP RH	26550-5WK0A	470.60 ?		
5	TAIL GATE INTERIOR FINISHER	90900-3VA0A	142.50 ?		
6	REAR W/SCREEN SEALANT	SEALANT - 4		NE	80.00
7	REAR PANEL	79100-3VA0A	597.60	3.6/10	
8	BOX-LUGGAGE REAR	84975-3VA0A	154.40 ?		
9	CARPET-LUGGAGE FLOOR	84903-3VA1A	468.60 ?		
10	TRUNK TOP PLATE	84992-3VA0A	74.30	NE	
11	EMBLEM REAR NOTE	90892-3VA0A	86.20	NE	
12	EMBLEM-REAR NISSAN	90890-3VA0A	70.00	NE	
13	STRIKER-TAIL GATE	90570-1HMOB	37.60	X	
14	TAIL GATE DOOR LOCK	90502-1HMOA	138.50	NE	
15	REAR W/SCREEN CORNER MLDG LH	90375-3VA0A	33.90	NE	
16	REAR W/SCREEN CORNER MLDG RH	90374-3VA0A	33.90	NE	
17	REAR W/SCREEN GLASS MLDG	90352-3VA0A	75.10	NE	
18	TAIL GATE W/STRIP	90830-3VA0A	73.60 ?		
19	TAIL GATE BACK DOOR	K010M-3VAMA	1099.10	NE	
20	SENSOR-REVERSE	SENSOR		should	200.00
21	REAR BUMPER STAY @ \$104.70 EACH	H5212-1HJMA	209.40 ?		
22	ENERGY ABSORBER REAR BUMPER	85090-5WJ0A	135.40 ?		
23	REAR BUMPER SIDE BRKT LH	85221-3VA0C	52.30	sent	
24	REAR BUMPER SIDE BRKT RH	85220-3VA0C	52.30	sent	
25	CLIP REAR BUMPER @ \$1.40 EACH	01553-10501	14.00	NE	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF7919T

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMAR
26 REAR BUMPER PASCIA	85022-5WJ0H	496.80		
SUB TOTAL		4986.70	0.00	390.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		997.34	0.00	0.00
GRAND TOTAL		3989.36	0.00	390.00
OVERALL TOTAL		4379.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF7919T

TOTAL LABOUR CHARGES	3285.00
TOTAL SPARE PARTS CHARGES	4379.36

GRAND TOTAL	7664.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.