

AUTOLUTION INDUSTRIAL PTE. LTD.

**AUTOLUTION INDUSTRIAL PTE LTD**  
**19 UBI ROAD 4**  
**SINGAPORE 408623**  
**TEL: 6490 9666 FAX: 6846 7483**

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0152/22

DATE : 26-APR-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : MDM ANG HAO @HONG HAO

ADDRESS : BLK 406B FERNVALE ROAD

#06-49

S(792406)

TELEPHONE NO : 8568 8652

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM

POLICY NO : DMPCSNW22231892101

VEHICLE NO : SMF7919T

MODEL CODE : TDWARDZE12EDAY520Z

MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018

ENGINE NO : HR12232415J

CHASSIS NO : JN1TAAE12Z0982396

MILEAGE : 79521 KM

DATE IN : 26/04/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 25/04/2022

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF7919T  
-----

| S/NO | JOB CODE | NATURE OF JOB                                                                                        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|------|----------|------------------------------------------------------------------------------------------------------|----------------------|------------------------------|
| 1    | ZZ/001   | LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR<br>FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER. | 1400.00              |                              |
| 2    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME.                                                                      | 1350.00              |                              |
| 3    | ZZ/003   | REMOVE AND INSTALL REAR W/SCREEN GLASS.                                                              | 180.00               |                              |
| 4    | ZZ/004   | REMOVE AND INSTALL TAIL GATE DOOR MECHANISM.                                                         | 80.00                |                              |
| 5    | ZZ/005   | APPLY SEALANT TO TAIL GATE BACK DOOR.                                                                | 100.00               |                              |
| 6    | ZZ/006   | PERFORM RUST PROOFING TO REAR PANEL.                                                                 | 120.00               |                              |
| 7    | ZZ/007   | REMOVE AND INSTALL REVERSE SENSOR - RENEW IF NEC<br>RESET AND FUNCTION TEST.                         | 55.00                |                              |
| 8    | ZZ/008   | RENEW REAR LICENCE PLATE.                                                                            |                      |                              |
|      |          | TOTAL LABOUR CHARGES                                                                                 | 3285.00              |                              |

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF7919T

|      |                                  | DAMAGED PARTS & PRICES |         |                   |
|------|----------------------------------|------------------------|---------|-------------------|
| S/NO | PARTS DESCRIPTION                | PARTS NUMBER           | NETT    | LIST S/NETT REMAR |
| 1    | SUNDRIES                         | NPN                    |         | 50.00             |
| 2    | REAR LICENCE PLATE               | RLP                    |         | 60.00             |
| 3    | REAR COMB LAMP LH                | 26555-5WK0A            | 470.60  |                   |
| 4    | REAR COMB LAMP RH                | 26550-5WK0A            | 470.60  |                   |
| 5    | TAIL GATE INTERIOR FINISHER      | 90900-3VA0A            | 142.50  |                   |
| 6    | REAR W/SCREEN SEALANT            | SEALANT - 4            |         | 80.00             |
| 7    | REAR PANEL                       | 79100-3VA0A            | 597.60  |                   |
| 8    | BOX-LUGGAGE REAR                 | 84975-3VA0A            | 154.40  |                   |
| 9    | CARPET-LUGGAGE FLOOR             | 84903-3VA1A            | 468.60  |                   |
| 10   | TRUNK TOP PLATE                  | 84992-3VA0A            | 74.30   |                   |
| 11   | EMBLEM REAR NOTE                 | 90892-3VA0A            | 86.20   |                   |
| 12   | EMBLEM-REAR NISSAN               | 90890-3VA0A            | 70.00   |                   |
| 13   | STRIKER-TAIL GATE                | 90570-1HM0B            | 37.60   |                   |
| 14   | TAIL GATE DOOR LOCK              | 90502-1HM0A            | 138.50  |                   |
| 15   | REAR W/SCREEN CORNER MLDG LH     | 90375-3VA0A            | 33.90   |                   |
| 16   | REAR W/SCREEN CORNER MLDG RH     | 90374-3VA0A            | 33.90   |                   |
| 17   | REAR W/SCREEN GLASS MLDG         | 90352-3VA0A            | 75.10   |                   |
| 18   | TAIL GATE W/STRIP                | 90830-3VA0A            | 73.60   |                   |
| 19   | TAIL GATE BACK DOOR              | K010M-3VAMA            | 1099.10 |                   |
| 20   | SENSOR-REVERSE                   | SENSOR                 |         | 200.00            |
| 21   | REAR BUMPER STAY @ \$104.70 EACH | H5212-1HJMA            | 209.40  |                   |
| 22   | ENERGY ABSORBER REAR BUMPER      | 85090-5WJ0A            | 135.40  |                   |
| 23   | REAR BUMPER SIDE BRKT LH         | 85221-3VA0C            | 52.30   |                   |
| 24   | REAR BUMPER SIDE BRKT RH         | 85220-3VA0C            | 52.30   |                   |
| 25   | CLIP REAR BUMPER @ \$1.40 EACH   | 01553-10501            | 14.00   |                   |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF7919T

|                                                       |                    | DAMAGED PARTS & PRICES |         |      |              |
|-------------------------------------------------------|--------------------|------------------------|---------|------|--------------|
| S/NO                                                  | PARTS DESCRIPTION  | PARTS NUMBER           | NETT    | LIST | S/NETT REMAR |
| 26                                                    | REAR BUMPER FASCIA | 85022-5WJ0H            | 496.80  |      |              |
| SUB TOTAL                                             |                    |                        | 4986.70 | 0.00 | 390.00       |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                    |                        | 997.34  | 0.00 | 0.00         |
| GRAND TOTAL                                           |                    |                        | 3989.36 | 0.00 | 390.00       |
| OVERALL TOTAL                                         |                    |                        | 4379.36 |      |              |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF7919T

-----  
TOTAL LABOUR CHARGES                    3285.00  
TOTAL SPARE PARTS CHARGES               4379.36  
-----  
GRAND TOTAL                               7664.36 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                                       :  
SURVEYED DATE                           :  
AUTHORIZED DATE                        :  
EXCESS CLAUSE                           :               0.00  
LIABILITY                                 :               0.00  
REMARKS                                   :

PLS NOTE : This estimate is based on visual inspection of the  
             affected vehicle. Should we require further labour  
             charges & spare parts in the process of repairs, we  
             shall inform you accordingly.