

Marcus

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0152/22
DATE : 26-APR-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MDM ANG HAO @HONG HAO
ADDRESS : BLK 406B FERNVALE ROAD
#06-49
S(792406)
TELEPHONE NO : 8568 8652

7 days.

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DMPCSNW22231892101
VEHICLE NO : SMF7919T
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12232415J
CHASSIS NO : JN1TAAE12Z0982396
MILEAGE : 81504 KM
DATE IN : 26/04/2022
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 25/04/2022

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF7919T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER.	1400.00	980.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	1350.00	1000.00
3	ZZ/003	REMOVE AND INSTALL REAR W/SCREEN GLASS.	180.00	150.00
4	ZZ/004	REMOVE AND INSTALL TAIL GATE DOOR MECHANISM.	80.00	80.00
5	ZZ/005	APPLY SEALANT TO TAIL GATE BACK DOOR.	100.00	100.00
6	ZZ/006	PERFORM RUST PROOFING TO REAR PANEL.	120.00	120.00
7	ZZ/007	REMOVE AND INSTALL REVERSE SENSOR - RENEW IF NEC RESET AND FUNCTION TEST.	55.00	55.00
8	ZZ/008	RENEW REAR LICENCE PLATE.		
TOTAL LABOUR CHARGES			3285.00	2485.00

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF7919T

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMAR
1	REAR END PANEL	79100-3VA0B	597.60			OK
2	CLIP REAR BUMPER @ \$1.40 EACH	01553-05933	14.00			OK
3	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
4	TRUNK TOP PLATE	84992-3VA0A	74.30			OK
5	EMBLEM REAR NOTE	90892-3VA0A	86.20			OK
6	EMBLEM-REAR NISSAN	90890-3VA0A	70.00			OK
7	TAIL GATE DOOR LOCK	90502-1HM0A	138.50			OK
8	REAR W/SCREEN CORNER MLDG LH	90375-3VA0A	33.90			OK
9	REAR W/SCREEN CORNER MLDG RH	90374-3VA0A	33.90			OK
10	REAR W/SCREEN GLASS MLDG	90352-3VA0A	75.10			OK
11	TAIL GATE BACK DOOR	K010M-3VAMA	1099.10			OK
12	SENSOR-REVERSE	SENSOR			200.00	OK
13	REAR BUMPER SIDE BRKT LH	85221-3VA0C	52.30			OK
14	REAR BUMPER SIDE BRKT RH	85220-3VA0C	52.30			OK
15	REAR BUMPER FASCIA	85022-5WJ0H	496.80			OK
SUB TOTAL			2824.00	0.00	280.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			564.80	0.00	0.00	
GRAND TOTAL			2259.20	0.00	280.00	
OVERALL TOTAL			2539.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMF7919T

NETT ITEM	2824.00
LESS 20.00%)	-564.80
NETT AMOUNT	2259.20
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	280.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	280.00
TOTAL LABOUR CHARGES	2485.00
TOTAL SPARE PARTS CHARGES	2539.20

TOTAL CHARGES	5024.20
LESS EXCESS	500.00

TOTAL	4524.20
ADD 7 % GST	316.69

GRAND TOTAL	4840.89
