

AIR DETAILS

Repairer Estimates

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **ComfortDelGro Engineering Pte Ltd/SHA1013G/26/04/2022 11:15**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>ca</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CLIPS <i>an</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY <i>sc</i>	20.00	0.00	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT <i>? Xan</i>	20.00	0.00	*394.80 FL X
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH <i>? Xan</i>	20.00	0.00	*138.10 FL X
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH <i>? Xan</i>	20.00	0.00	*138.10 FL X
7	1		*REAR BUMPER FOG LAMP <i>sc</i>	20.00	0.00	*201.50 FL
8	1		*REAR BUMPER LICENCE LAMP <i>? Xan</i>	20.00	0.00	*85.30 FL X
9	1		*ANTENNA ASSY SMARTKEY <i>? Xan</i>	20.00	0.00	*40.50 FL X
10	1		*REAR BUMPER TOWING COVER <i>X</i>	20.00	0.00	*94.60 FL X
11	1		*REAR BUMPER SIDE BRACKET LH <i>? Xan</i>	20.00	0.00	*55.80 FL X
12	1		*REAR BUMPER SIDE BRACKET RH <i>? Xan</i>	20.00	0.00	*55.80 FL X
13	1		*REAR BUMPER LOWER CTR MOULDING <i>sc</i>	20.00	0.00	*155.00 FL
14	1		*BOOTLID <i>repair X</i>	20.00	0.00	*2,549.70 FL XR
15	1		*BOOTLID HYUNDAI PLATE <i>sc</i>	20.00	0.00	*24.30 FL
16	1		*EMBLEM HYBRID <i>an</i>	20.00	0.00	*24.30 FL
17	1		*EMBLEM - IONIQ <i>an</i>	20.00	0.00	*31.30 FL
18	1		*REAR FENDER ADVERTISEMENT STICKER LH <i>an</i>	0.00	0.00	*100.00 F S/N
19	1		*REAR FENDER ADVERTISEMENT STICKER RH <i>an</i>	0.00	0.00	*100.00 F S/N
20	1		*BOOTLID ADVERTISEMENT STICKER <i>an</i>	0.00	0.00	*100.00 F S/N
21	1		*REAR NUMBER PLATE WITH TRIM COVER <i>com</i>	0.00	0.00	*55.00 F S/N
22	1		*BOOTLID COMFORT TEL NO STICKER <i>an</i>	0.00	0.00	*40.00 F S/N
23	1		*BOOTLID COMFORT LOGO STICKER <i>an</i>	0.00	0.00	*30.00 F S/N
24	1		*BOOTLID COMFORT APP STICKER <i>an</i>	0.00	0.00	*30.00 F S/N
25	1		*REAR BUMPER REVERSE SENSOR <i>? Xan</i>	0.00	0.00	*180.00 F X

F=Franchise part, L=ListItemDisc.

Sub Total (S\$) **5,556.75**

- List Item Discount on L Items (S\$) **984.35**

Total Parts (S\$) 4,572.40

ComfortDelGro Engineering Pte Ltd/SHA1013G/26/04/2022 11:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
			11
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	800 800.00
2	SPRAY PAINTING CHARGE	New	500 600.00
3	CHK ALL LIGHTING	New	MX 60.00
4	TUFF KOTE	New	MX 60.00
5	REMOVE/REFIX REVERSE SENSOR	New	40 80.00
Gross Labour Cost (S\$)			1,600.00

ComfortDelGro Engineering Pte Ltd/SHA1013G/26/04/2022 11:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Rasul
Hp 90010068
4 days
4S
27/04/22 @ 1555

Reg after repair

1095.24
455.00
11.00
1065.00

2626.24
20%
2100.99

4S - 2,050