

NOT Notarised
C/Rep @ 5100p

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD145A

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 APR 2022

SHD145A

VF1ABL15AUC282250

200303878K

RENAULT

LATITUDE

26/04/2022

GBD2236D/CHINA

01/09/2015

PART		LIST	
1	DOOR PANEL FRT LH	\$	R 2,844.66 X
1	DOOR HINGE UPPER FRT LH	\$	R 274.50 X
1	DOOR HINGE LOWER FRT LH	\$	R 300.55 X
1	ROCKER PANEL OUTER LH	\$	R 1,184.99 X
1	FENDER PANEL INNER FRT LH	\$	R 858.30 X
1	FENDER PANEL FRT LH	\$	R 437.10 ✓
1	WHEELARCH FRT LH	\$	CM 191.40 ✓
1	BUMPER COVER FRT	\$	CM 747.20 ✓
1	BUMPER BEAM FRT	\$	R 663.70 X
1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
1	BUMPER RETAINER FRT LH	\$	CM 101.40 ✓
1	BUMPER SPOILER FRT	\$	D/Y 344.70 ✓
1	BUMPER GRILLE LOWER FRT	\$	Sn Des 147.00 X
1	BUMPER FOG LAMP GRILLE LH	\$	D/Y 207.21 ✓
1	BONNET	\$	R 1,312.70 ✓
1	BONNET HINGE LH	\$	R 237.40 X
1	BONNET HINGE RH	\$	R 237.40 X
1	AIR CLEANER LOWER	\$	SL 271.26 X
1	AIR CLEANER HOSE	\$	SL 175.85 X
1	AIR CLEANER BOX	\$	SL 464.20 X
1	RADIATOR GRILLE	\$	CM 969.90 ✓
1	RADIATOR GRILLE BADGE "RENAULT"	\$	R 225.36 ✓
1	FRAME FULL SUPPORT PANEL	\$	SL 592.70 X
1	RADIATOR GRILLE FRAME	\$	SL 686.00 X
1	HEADLAMP LH	\$	Br 743.60 ✓
1	HEADLAMP PANEL FRT LH	\$	R 128.30 X

Trans-cab Auto Services Pte Ltd**AAD2204-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD145A

TOTAL	\$	6,838.70
10%	\$	683.87
	\$	6,154.83

Special Nett

1 DOOR TRIM CLIP	\$	nn	70.00	X
1 DOOR MOULDING CLIP	\$	nn	70.00	X
1 DOOR STICKER TRANSCAB	\$	nn	100.00	X
1 FRONT DOOR ADVERTISEMENT	\$	nn	200.00	X
1 DOOR STICKER CLASSIC	\$	nn	100.00	X
1 FRT BUMPER CLIP	\$	nn	65.00	✓
1 FENDER CLIP	\$	nn	70.00	✓
1 FENDER LINER CLIP	\$	nn	65.00	X
TOTAL	\$		740.00	

TOTAL PARTS \$ 6,894.83**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	601
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	1,400.00	8801
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	5001
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

TOTAL \$ 4,360.00**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey left side after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD145A

Over All Total	\$	<u>11,254.83</u>
----------------	----	------------------

(LUMPSUM) Repair Days

~~20~~ Days

3 days