



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0346/2022/JT
DATE : 28-Apr-22
WIP : 21885

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : SMJ 3225 S

ECICS Limited

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER TWO
SINGAPORE 038987

Attn: Motor Claims Dept

Tel: 65 6337 4779 - Fax: 6303 0182

OWNER'S NAME : MR CHIA WOUNH TIH
ADDRESS : BLK 655A JURONG WEST ST 64
#07-160
SINGAPORE 641665
TELEPHONE : HP +65 83286968
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10683669R00
VEHICLE NO : SLL 1780 U
MODEL CODE : VOLKSWAGEN CADDY 1.4
MODEL YEAR : 16/2/2017
ENGINE NO : CZC 640111
CHASSIS NO : WV2ZZZ2KZHX070933
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-22
PLACE OF ACCIDENT : AYE TOWARDS CITY (NEAR CLEMENTI ROAD EXIT)



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	/
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 800.00	500
4	TO RESPRAY FRONT BUMPER.	\$ 600.00	500
SUB TOTAL LABOUR CHARGES		: \$ 2,480.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 360.00 /	
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$ 480.00 /	
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00 100	
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00 ? x	
SUB TOTAL LABOUR CHARGES		: \$ 1,720.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	? X
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 3 X 500	\$ 3,500.00	1500 3000
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR FENDER. 3 X 500	\$ 3,000.00	1500 2000
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 150.00	/
TOTAL LABOUR CHARGES (FRONT & REAR)		: \$ 12,250.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>x R</i>	1	\$	1,560.00	
2	FRONT BUMPER SUPPORT ELEMENT - LH / RH <i>? X nn</i>	2	\$	556.00	
3	LOCKING CLIP <i>? X nn</i>	8	\$	35.00	
4	FRONT BUMPER ATTACHMENT PARTS <i>X nn</i>	1	\$	13.00	
5	FRONT BUMPER SPOILER <i>X nn</i>	1	\$	679.00	
6	FRONT BUMPER TOWING EYE <i>X nn</i>	1	\$	68.00	
7	FRONT BUMPER GUIDE FRAME - LH / RH <i>X nn</i>	2	\$	88.00	
8	RADIATOR GRILLE <i>? X nn</i>	1	\$	580.00	
9	VW EMBLEM <i>? X nn</i>	1	\$	139.00	
10	RADIATOR GRILLE VENT <i>/ cut ? X nn</i>	1	\$	361.00	✓
11	FRONT BUMPER CHROME TRIM <i>? X nn</i>	1	\$	318.00	
12	FRONT BUMPER FOG LAMPS COVER - LH / RH <i>X nn</i>	2	\$	332.00	
13	FRONT BUMPER FOG LAMPS TRIM - LH / RH <i>X nn</i>	2	\$	170.00	
14	FRONT BUMPER GUIDE PROFILE - LH / RH <i>? X nn</i>	2	\$	186.00	
15	FRONT BUMPER FOAM FILLER PIECE - LOWER <i>? X nn</i>	1	\$	95.00	
16	FRONT BUMPER FOAM FILLER PIECE - CENTER <i>? X nn</i>	1	\$	102.00	
17	FRONT BUMPER CROSS MEMBER - LOWER <i>? X nn</i>	1	\$	330.00	
18	FRONT BUMPER SIDE REINFORCEMENT <i>? X nn</i>	1	\$	953.00	
19	OUTSIDE TEMPERATURE SENSOR BRACKET <i>? X nn</i>	1	\$	6.00	
20	LOCK CARRIER SUPPORT - CENTER <i>? X nn</i>	1	\$	158.00	
SUB TOTAL SPARE PARTS			:	\$	6,729.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HEADLIGHT - LH / RH ✓ nn	2	\$	5,572.00	
22	FOG LAMPS - LH / RH ✓ nn	2	\$	654.00	
23	RADIATOR AIR GUIDE INNER - LH / RH ✓ nn	2	\$	62.00	
SUB TOTAL SPARE PARTS		:	\$	6,288.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER / BR	1	\$	1,086.00	✓
2	REAR BUMPER FIXING PARTS ? X nn	1	\$	51.00	
3	REAR BUMPER TOW HITCH COVER CAP ? X nn	1	\$	76.00	
4	REAR BUMPER LOWER ? DD	1	\$	1,022.00	✓
5	REAR GUIDE PROFILE - LH / RH ? BR	1 2	\$	98.00	49 ✓
6	REAR PARKING AID SENSOR BRACKET / MK	1	\$	124.00	✓
7	REAR PARKING AID SENSOR - CENTER ? X nn	2	\$	530.00	
8	REAR PARKING AID SENSOR - LH ? X nn	2	\$	530.00	
9	REAR PARKING AID SENSOR CAP / MK	4	\$	47.00	✓
10	REAR PARKING AID SENSOR SEAL RING - MK X nn	4	\$	10.00	
11	REAR BUMPER WIRING SET ? X nn	1	\$	464.00	
12	TAIL LIGHT - LH / RH / BR	(2)	\$	636.00	✓
13	REAR LIGHT REFLECTOR - LH / RH - BR	1 2	\$	156.00	78 ✓
14	LICENCE PLATE LIGHT ? X nn	2	\$	219.00	
15	REAR LID / DD	1	\$	3,510.00	✓
16	ANTI CORROSION WAX X nn	1	\$	51.00	
17	REAR LID SEAL / Tn	1	\$	251.00	✓
18	REAR LID LOOP ? X nn	1	\$	144.00	
19	REAR LID LOCK ACTUATOR WITH CAMERA ? X nn	1	\$	1,340.00	
20	REAR LID LOCK MICROSWITCH ? BT	1	\$	109.00	✓
SUB TOTAL SPARE PARTS			:	\$	10,454.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID LOCK ACTUATOR WITH CAMERA COVER	1 X nn	28.00	
22	REAR LID STRIKER PLATE	1 BT	66.00	✓
23	REAR LID GUIDE SECTION	2 X nn	82.00	
24	BONNET ABSORBER	2 X nn	273.00	
25	REAR LID HINGE	2 X nn	TBC	
26	CADDY EMBLEM	1 m	81.00	✓
27	VW EMBLEM	1 hC	114.00	✓
28	TSI EMBLEM	1 hC	100.00	✓
29	REAR LID TRIM - CENTER	1 BR	489.00	✓
30	REAR LID LOAD EDGE PROTECTION	1 X nn	414.00	
31	REAR WINDSCREEN	1 X BR (inconsistent)	875.00	
32	2K PANE ADHESIVE SET	1 X nn	105.00	
33	PRIMER	1 X nn	22.00	
34	CLEANING SOLUTION	1 X nn	74.00	
35	APPLICATOR ADHESIVE	1 X nn	8.00	
36	APPLICATOR	1 X nn	6.00	
37	ACTIVATOR	1 X nn	19.00	
38	REAR END PANEL	1 DD	471.00	✓
39	REAR END PANEL LOCK CARRIER - CENTER	1 DD	184.00	✓
40	REAR END PANEL LOCK CARRIER - LH / RH	1 DD	170.00	85
SUB TOTAL SPARE PARTS			\$ 3,579.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	TAIL LIGHT MOUNTING - LH ? X nn	1	\$	84.00	
42	REAR LID TRIM PANEL ? X nn	1	\$	93.00	
43	LUGGAGE COMPARTMENT COVER ? X nn	1	\$	717.00	
44	REAR END PANEL UPPER TRIM ? BR	1	\$	224.00	✓
45	FLOORING - CENTER ? X nn	1	\$	1,236.00	
46	REAR SILENCER X nn	1	\$	183.00	
47	ARYLIC SEALANT ? NEC	S/N	\$	180.00	✓
48	CAVITY WAX ? NEC	S/N	\$	140.00	✓
49	STONE CHIP ? NEC	S/N	\$	180.00	✓
50	METAL FILLER POWDER ? NEC	S/N	\$	280.00	✓
51	REAR WIDNSCREEN SEALANT / ncc	S/N	\$	200.00	✓
52	FRONT NO PLATE / B7	S/N	\$	60.00	✓
53	REAR NO PLATE / B7	S/N	\$	60.00	✓
54	SUNDRIES ? NEC		\$	500.00	47.20 ✓
TOTAL SPARE PARTS (FRONT & REAR)		:	\$	31,187.00	
TOTAL LABOUR CHARGES (FRONT & REAR)		:	\$	12,250.00	
GRAND TOTAL		:	\$	43,437.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
: 4/5/22, 4:10pm
:
:
:
:

Wm NL
PIP
My Policy
10 yrs

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT