

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0346/2022/JT
DATE : 28-Apr-22
WIP : 21885

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : SMJ 3225 S

ECICS Limited
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER TWO
SINGAPORE 038987
Attn: Motor Claims Dept
Tel: 65 6337 4779 - Fax: 6303 0182

Dear Steve,

We took 14 days to repair this vehicle.

OWNER'S NAME : MR CHIA WOUNH TIH
ADDRESS : BLK 655A JURONG WEST ST 64
#07-160
SINGAPORE 641665
TELEPHONE : HP +65 83286968
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10683669R00
VEHICLE NO : SLL 1780 U
MODEL CODE : VOLKSWAGEN CADDY 1.4
MODEL YEAR : 16/2/2017
ENGINE NO : CZC 640111
CHASSIS NO : WV2ZZZ2KZHX070933
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-22
PLACE OF ACCIDENT : AYE TOWARDS CITY (NEAR CLEMENTI ROAD EXIT)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	280.00	\$	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	800.00	\$	500.00
4	TO RESPRAY FRONT BUMPER.	\$	600.00	\$	500.00
SUB TOTAL LABOUR CHARGES		:	\$ 2,480.00	\$	1,280.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,280.00
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	360.00	\$ 360.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	\$ 480.00
4	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$	200.00	\$ 100.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	
SUB TOTAL LABOUR CHARGES		:	\$ 1,720.00	\$ 2,500.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1780 U - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 2,500.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	\$ 3,000.00
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR FENDER.	\$ 3,000.00	\$ 2,000.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 150.00	\$ 150.00
TOTAL LABOUR CHARGES (FRONT & REAR)		: \$ 12,250.00	\$ 7,650.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,560.00	
2	FRONT BUMPER SUPPORT ELEMENT - LH / RH	2	\$ 556.00	
3	LOCKING CLIP	8	\$ 35.00	
4	FRONT BUMPER ATTACHMENT PARTS	1	\$ 13.00	
5	FRONT BUMPER SPOILER	1	\$ 679.00	
6	FRONT BUMPER TOWING EYE	1	\$ 68.00	
7	FRONT BUMPER GUIDE FRAME - LH / RH	2	\$ 88.00	
8	RADIATOR GRILLE	1	\$ 580.00	
9	VW EMBLEM	1	\$ 139.00	
10	RADIATOR GRILLE VENT	1	\$ 361.00	\$ 361.00
11	FRONT BUMPER CHROME TRIM	1	\$ 318.00	
12	FRONT BUMPER FOG LAMPS COVER - LH / RH	2	\$ 332.00	
13	FRONT BUMPER FOG LAMPS TRIM - LH / RH	2	\$ 170.00	
14	FRONT BUMPER GUIDE PROFILE - LH / RH	2	\$ 186.00	
15	FRONT BUMPER FOAM FILLER PIECE - LOWER	1	\$ 95.00	
16	FRONT BUMPER FOAM FILLER PIECE - CENTER	1	\$ 102.00	
17	FRONT BUMPER CROSS MEMBER - LOWER	1	\$ 330.00	
18	FRONT BUMPER SIDE REINFORCEMENT	1	\$ 953.00	
19	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 6.00	
20	LOCK CARRIER SUPPORT - CENTER	1	\$ 158.00	
SUB TOTAL SPARE PARTS		:	\$ 6,729.00	\$ 361.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 361.00
21	HEADLIGHT - LH / RH	2	\$ 5,572.00	
22	FOG LAMPS - LH / RH	2	\$ 654.00	
23	RADIATOR AIR GUIDE INNER - LH / RH	2	\$ 62.00	
SUB TOTAL SPARE PARTS		:	\$ 6,288.00	\$ 361.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	361.00
1	REAR BUMPER	1	\$ 1,086.00	\$	1,086.00
2	REAR BUMPER FIXING PARTS	1	\$ 51.00		
3	REAR BUMPER TOW HITCH COVER CAP	1	\$ 76.00		
4	REAR BUMPER LOWER	1	\$ 1,022.00	\$	1,022.00
5	REAR GUIDE PROFILE - LH / RH	2	\$ 98.00	\$	49.00
6	REAR PARKING AID SENSOR BRACKET	1	\$ 124.00	\$	124.00
7	REAR PARKING AID SENSOR - CENTER	2	\$ 530.00		
8	REAR PARKING AID SENSOR - LH	2	\$ 530.00		
9	REAR PARKING AID SENSOR CAP	4	\$ 47.00	\$	47.00
10	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00		
11	REAR BUMPER WIRING SET	1	\$ 464.00		
12	TAIL LIGHT - LH / RH	2	\$ 636.00	\$	636.00
13	REAR LIGHT REFLECTOR - LH / RH	2	\$ 156.00	\$	78.00
14	LICENCE PLATE LIGHT	2	\$ 219.00		
15	REAR LID	1	\$ 3,510.00	\$	3,510.00
16	ANTI CORROSION WAX	1	\$ 51.00		
17	REAR LID SEAL	1	\$ 251.00	\$	251.00
18	REAR LID LOOP	1	\$ 144.00		
19	REAR LID LOCK ACTUATOR WITH CAMERA	1	\$ 1,340.00		
20	REAR LID LOCK MICROSWITCH	1	\$ 109.00	\$	109.00
SUB TOTAL SPARE PARTS		:	\$ 10,454.00	\$	7,273.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
<i>c/f</i>				\$ 7,273.00
21	REAR LID LOCK ACTUATOR WITH CAMERA COVER	1	\$ 26.00	
22	REAR LID STRIKER PLATE	1	\$ 66.00	\$ 66.00
23	REAR LID GUIDE SECTION	2	\$ 82.00	
24	BONNET ABSORBER	2	\$ 273.00	
25	REAR LID HINGE	2	TBC	
26	CADDY EMBLEM	1	\$ 81.00	\$ 81.00
27	VW EMBLEM	1	\$ 114.00	\$ 114.00
28	TSI EMBLEM	1	\$ 100.00	\$ 100.00
29	REAR LID TRIM - CENTER	1	\$ 489.00	\$ 489.00
30	REAR LID LOAD EDGE PROTECTION	1	\$ 414.00	
31	REAR WINDSCREEN	1	\$ 875.00	
32	2K PANE ADHESIVE SET	1	\$ 105.00	
33	PRIMER	1	\$ 22.00	
34	CLEANING SOLUTION	1	\$ 74.00	
35	APPLICATOR ADHESIVE	1	\$ 8.00	
36	APPLICATOR	1	\$ 6.00	
37	ACTIVATOR	1	\$ 19.00	
38	REAR END PANEL	1	\$ 471.00	\$ 471.00
39	REAR END PANEL LOCK CARRIER - CENTER	1	\$ 184.00	\$ 184.00
40	REAR END PANEL LOCK CARRIER - LH / RH	2	\$ 170.00	\$ 85.00
SUB TOTAL SPARE PARTS			\$ 3,579.00	\$ 8,863.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1780 U - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	8,863.00
41	TAIL LIGHT MOUNTING - LH	1	\$ 84.00		
42	REAR LID TRIM PANEL	1	\$ 93.00		
43	LUGGAGE COMPARTMENT COVER	1	\$ 717.00		
44	REAR END PANEL UPPER TRIM	1	\$ 224.00	\$	224.00
45	FLOORING - CENTER	1	\$ 1,236.00		
46	REAR SILENCER	1	\$ 183.00		
47	ARYLIC SEALANT	S/N	\$ 180.00	\$	180.00
48	CAVITY WAX	S/N	\$ 140.00	\$	140.00
49	STONE CHIP	S/N	\$ 180.00	\$	180.00
50	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
51	REAR WIDNSCREEN SEALANT	S/N	\$ 200.00	\$	200.00
52	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
53	REAR NO PLATE	S/N	\$ 60.00	\$	60.00
54	SUPPLEMENTARY		\$ 321.00	\$	321.00
54	SUNDRIES		\$ 500.00	\$	47.20
TOTAL SPARE PARTS (FRONT & REAR)			\$ 31,508.00	\$	10,555.20
TOTAL LABOUR CHARGES (FRONT & REAR)			\$ 12,250.00	\$	7,650.00
GRAND TOTAL			\$ 43,758.00	\$	18,205.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-22/12/22



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

ECICS Limited
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER TWO
SINGAPORE 038987
Attn: Motor Claims Dept
Tel: 65 6337 4779 - Fax: 6303 0182

Estimate No. PA/TP/0346/2022/JT
Date 1-Jun-22
Service Advisor CHANG
Pages 1 of 1
Regn No SLL 1780 U
Model No VOLKSWAGEN CADDY 1.4

Quantity	Description		Unit Price	Amount
Parts				
1	REAR FENDER FUNCTION PLATE - LH	1	\$ 105.00	\$ 105.00
2	HINGE REINFORCEMENT FOR REAR LIF - LH	1	\$ 51.00	\$ 51.00
3	HIGH-LEVEL BRAKE LIGHT WITH SPRAY JET	1	\$ 165.00	\$ 165.00
GRAND TOTAL			\$ 321.00	\$ 321.00

For Premium Automobiles Pte Ltd

Authorised Signature