



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22004022/Bqy3e2 Date: 15/02/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 146Z	Veh. Inspected	SGX 6206A	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/04/22/7022	Excess (\$)	0.00	
Assign From	Hua Yen	Assign Date	28/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200K	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	WDB2110412B115220	Colour	SILVER	
Odometer	290349 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	TOYO	5 mm	
L/H Front Tyre	245/45 R17	TOYO	5 mm	
R/H Rear Tyre	245/45 R17	TOYO	5 mm	
L/H Rear Tyre	245/45 R17	TOYO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2022	Inspection Date	29/04/2022	
Survey held at	MCR MOTORS PTE LTD 8 Kaki Bukit Ave 4 #01-54, Premier @ Kaki Bukit Singapore 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	