

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE : _____

Date of Survey : _____

Date of ReSurvey: _____

Contacts : _____

Vehicle Nos : SGX 6206A
 Made : Mercedes Benz
 Model : E200K
 Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Bumper	1	\$ 1,670.00	\$ 1,670.00	✓
2	Rear Bumper Chrome Moulding RH	1	\$ 154.00	\$ 154.00	✓
3	Rear Bumper Chrome Moulding LH	1	\$ 154.00	\$ 154.00	✓
4	Rear Bumper Chrome Moulding Centre	1	\$ 224.00	\$ 224.00	✓
5	Rear Bumper Side Retainer RH	1	\$ 47.00	\$ 47.00	✓
6	Rear Bumper Side Retainer LH	1	\$ 47.00	\$ 47.00	✓
7	Rear Bumper Rivets	10	\$ 6.00	\$ 60.00	40 ✓
8	Rear Bumper Centre Bracket	1	\$ 265.00	\$ 265.00	✓
9	Rear Bumper Reinforcement	1	\$ 655.00	\$ 655.00	✓
10	Rear Bumper Lower Bracket RH	1	\$ 18.00	\$ 18.00	
11	Rear Bumper Lower Bracket LH	1	\$ 18.00	\$ 18.00	
12	Rear Bumper Tow Cover	1	\$ 26.00	\$ 26.00	
13	Rear Bootlid	1	\$ 1,928.00	\$ 1,928.00	
14	Rear Bootlid Emblem	1	\$ 48.00	\$ 48.00	
15	Rear Bootlid "E 200" Emblem	1	\$ 76.00	\$ 76.00	
16	Rear Bootlid "Kompressor" Emblem	1	\$ 98.00	\$ 98.00	
17	Rear Bootlid "C&C" Emblem	1	\$ 50.00	\$ 50.00	
18	Rear Bootlid Garnish with Chrome Moulding	1	\$ 587.00	\$ 587.00	
19	Rear Bootlid Top Lock	1	\$ 225.00	\$ 225.00	
20	Rear Bootlid Lower Lock	1	\$ 162.00	\$ 162.00	
21	Rear Bootlid Lower Lock Cover	1	\$ 78.00	\$ 78.00	
22	Rear Bootlid Weatherstrip	1	\$ 176.00	\$ 176.00	
23	Rear Taillamp Assembly RH	1	\$ 600.00	\$ 600.00	✓
24	Rear Taillamp Assembly LH	1	\$ 600.00	\$ 600.00	
25	Rear Taillamp Side Garnish RH	1	\$ 84.00	\$ 84.00	✓
26	Rear Taillamp Side Garnish LH	1	\$ 84.00	\$ 84.00	
27	Rear End Panel	1	\$ 786.00	\$ 786.00	✓
28	Rear End Panel Top Garnish	1	\$ 225.00	\$ 225.00	✓
29	Rear Spare Tyre Panel Top Board	1	\$ 287.00	\$ 287.00	
30	Rear Fender Inner Trim RH	1	\$ 342.00	\$ 342.00	
31	Rear Fender Inner Trim LH	1	\$ 342.00	\$ 342.00	
32	Rear Silencer Box	1	\$ 2,059.00	\$ 2,059.00	

33	Rear Silencer Box Mounting	2	\$ 28.00	\$ 56.00	} NDX
34	Rear Exhaust Chrome Pipe	1	\$ 185.00	\$ 185.00	
4951 -10% 4455.90				Parts Sub Total :	\$ 12,416.00
10%				Discount	\$ 1,241.60
				PARTS TOTAL :	\$ 11,174.40

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ 50.00	NDX
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 50.00 30.00	NECV
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ 50.00	NNX
4	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00 30.00	NECV
5	Rear Fender Inner Trim Clips - Set	1	\$ 80.00	\$ 80.00	} NNX
6	Rear Bootlid Sealant	1	\$ 150.00	\$ 150.00	
7	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00 40.00	NECV
8	Rear Bumper Reverse Sensor - Set	1	\$ 450.00	\$ 450.00 200.00	SCV
9	Rear Bootlid Reverse Camera	1	\$ 500.00	\$ 500.00	NDX
300				SPECIAL NETT TOTAL :	\$ 1,530.00

Nos.	LABOUR	S\$	
1	To Panel Beat, Remove & Refix Parts	\$ 1200.00 1,600.00	}
2	To Spray Paint Affected Areas	\$ 600.00 1,600.00	
3	Wiring & Bulb Check	\$ 100.00	} NNX
4	To Transfer Rear Bootlid Mechanism	\$ 150.00	
5	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00 60.00	}
6	To Remove & Refix Rear Bootlid Reverse Camera	\$ 150.00	
7	To Remove & Refix Rear Exhaust Pipe	\$ 150.00	} NNX
8	To apply anti rust on affected parts	\$ 100.00	
9	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00 50.00	}
10	To Conduct Water Leak Test	\$ 100.00	
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00	} NNX
		LABOUR TOTAL :	\$ 4,700.00

Survey & Resurvey

1910

29/4/2022

TCim lun

6665.90

L/S - 5332.72
= 5350

1435 hrs

PARTS TOTAL :	\$ 11,174.40
SPECIAL NETT TOTAL :	\$ 1,530.00
LABOUR TOTAL :	\$ 4,700.00
GRAND TOTAL :	\$ 17,404.40

Lump sum repair
Repair days 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: