



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CHUAN LIM CONSTRUCTION PTE LTD

20 SENOKO DR

SINGAPORE 758207

Insured CHUAN LIM CONSTRUCTION PTE LTD

Policy D-21098228MCVT

Damaged Vehicle No: XE3541A

Final Bill

GST Reg. No: 19-9800107D

Date: 3/11/2022

Our Case Ref. SC22/03/039/4CL-TP

Accident Date 21/3/2022

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	NUMBER PLATE	1 PC	\$25.00	-	\$25.00
2	ROUND STICKER	1 PC	\$15.00	-	\$15.00
3	REAR RHS TAIL LAMP	1 PC	\$300.00	-	\$300.00
4	SAFETY GUARD BRACKET	2 PC	\$450.00	-	\$900.00
<u>Labour Charges</u>					
1	LABOUR TO REMOVE,REPAIR AND REINSTALL FOR REAR PORTION	1	\$1,600.00	-	\$1,600.00
2	LABOUR TO RESPRAY REAR PORTION	1	\$640.00	-	\$640.00
3	LABOUR FOR WIRING	1	\$50.00	-	\$50.00
Sub Total					\$ 3,530.00
Lump Sum					\$ 2,800.00
GST (8%)					\$ 224.00
Total Amount					\$ 3,024.00

Authorised Signature