



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CHUAN LIM CONSTRUCTION PTE LTD
20 SENOKO DR
SINGAPORE 758207
Insured CHUAN LIM CONSTRUCTION PTE LTD
Policy D-21098228MCVT

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 28/4/2022
Our Case Ref. SC22/03/039/4CL-TP
Accident Date 21/3/2022

Damaged Vehicle No: XE3541A

| S/no | Description | QTY | Price | Disc | Amount |
|---|---|------|------------|--------------|--------------------------------------|
| Replaced Parts | | | | | |
| 1 | NUMBER PLATE <i>lt ✓</i> | 1 PC | \$25.00 | - | \$25.00 |
| 2 | ROUND STICKER <i>na ✓</i> | 1 PC | \$15.00 | - | \$15.00 |
| 3 | REAR RHS TAIL LAMP <i>cm ✓</i> | 1 PC | \$300.00 | - | \$300.00 |
| 4 | REAR BUMPER <i>repair</i> | 1 PC | \$750.00 | - <i>xR</i> | \$750.00 |
| 5 | REAR SAFETY GUARD PANEL <i>repair</i> | 1 PC | \$950.00 | - <i>xR</i> | \$950.00 |
| 6 | SAFETY GUARD BRACKET <i>lt ✓</i> | 2 PC | \$450.00 | - | \$900.00 |
| Labour Charges | | | | | |
| 1 | LABOUR FOR REAR PORTION <i>@640 x 2.5</i> | 1 | \$3,200.00 | - | <i>1700</i> \$3,200.00 |
| 2 | LABOUR FOR PAINTING <i>@640</i> | 1 | \$1,200.00 | - <i>640</i> | \$1,200.00 |
| 3 | LABOUR FOR WIRING | 1 | \$80.00 | - <i>50</i> | \$80.00 |
| <i>1116</i> <i>2390</i> <i>3506</i> <i>20%</i> <i>2804.80</i> | | | | | <i>4/5 - \$2,800 / 4 days</i> |
| Sub Total | | | | | \$ 7,420.00 |

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rearu
Hf 90010068
4 days
4/5

11/10/22 @ 1400

Rearu after repair