

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22004034/KTCN2**Date:** 06/06/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000210
Claimant Vehicle No :	SHD5483R	Insured Vehicle No :	SLN6840L
Date of Loss:	26/04/2022	Nature of Claim:	TP
		Claim No:	M2202045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5483R	Engine No:	2ZR2B99305
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU603079185
Reg. Date:	25/01/2019 (Man. Year: 2018)	Odometer:	516488 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,535.05	4,334.25	8,200.80	65.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,920.00	1,850.00	7,070.00	79.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,455.05	6,184.25	15,270.80	71.18
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	21,455.05	4,950.00	16,505.05	76.93
+ GST 7.00/7.00% (S\$)	1,501.85	346.50	1,155.35	76.93
Nett Amount (S\$)	22,956.90	5,296.50	17,660.40	76.93

INSPECTION

Date of Assignment:	04/05/2022		
Date Inspected:	28/04/2022	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2022)**Parts:** 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHD5483R)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER REAR BUMPER	Bent	442.60 FL	-	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 FL
3	1		*COVER,REAR BUMPER,LOWER	Missing	15.40 FL	-	*15.40 FL
4	1		*GUARD,REAR BUMPER,CENTER	Bent	576.30 FL	-	*576.30 FL
5	1		*RETAINER,REAR BUMPER SIDE,LH	Mtg Cracked	116.50 FL	-	*116.50 FL
6	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	117.70 FL	-	*- FL
7	1		*FILLER,REAR BUMPER EXTENSION,RH	Serviceable	123.70 FL	-	*- FL
8	1		*FILLER,REAR BUMPER EXTENSION,LH	Serviceable	123.70 FL	-	*- FL
9	1		*LENS & BODY,REAR COMBINATION LAMP,LH (UPPER)	Cracked	443.30 FL	-	*443.30 FL
10	1		*LENS AND BODY,REAR LAMP,LH (LOWER)	Serviceable	502.00 FL	-	*- FL
11	1		*LENS & BODY,REAR COMBINATION LAMP,RH (UPPER)	Cracked	451.80 FL	-	*451.80 FL
12	1		*LENS AND BODY,REAR LAMP,RH (LOWER)	Serviceable	502.00 FL	-	*- FL
13	1		*BOX,DECK FLOOR,RH	Serviceable	313.60 FL	-	*- FL
14	1		*BOX,DECK FLOOR,LH	Serviceable	313.00 FL	-	*- FL
15	1		*BOX,DECK FLOOR,REAR	Serviceable	105.80 FL	-	*- FL
16	1		*COVER,FLOOR UNDER.NO 1 LH	Serviceable	175.10 FL	-	*- FL
17	1		*COVER,FLOOR UNDER.NO 2 RH	Serviceable	241.90 FL	-	*- FL
18	1		*COVER,REAR FLOOR CTR	Missing	229.90 FL	-	*229.90 FL
19	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
20	1		*PAN,REAR FLOOR	Repair	583.40 FL	-	*- FL
21	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	-	*- FL
22	1		*LOCK ASSY,BACK DOOR,W/COURTESY LAMP SWITCH	Repair	467.00 FL	-	*- FL
23	1		*SWITCH ASSY,BACK DOOR OPENER	Serviceable	179.10 FL	-	*- FL
24	1		*SPOILER,SUB ASSY,REAR	Serviceable	1,575.40 FL	-	*- FL
25	1		*PANEL SUB-ASSY,BACK DOOR	Bent	1,147.80 FL	-	*1,147.80 FL
26	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Cracked	925.60 FL	-	*925.60 FL
27	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	-	*- FL
28	1		*WEATHERSTRIP,BACK DOOR	Serviceable	372.30 FL	-	*- FL
29	1		*BOARD,BACK DOOR TRIM	Serviceable	225.20 FL	-	*- FL
30	1		*BOARD,REAR FLOOR,NO,1	Serviceable	519.00 FL	-	*- FL
31	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	-	*- FL
32	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	-	*- FL
33	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	-	*- FL
34	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	-	*- FL
35	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.90 FL	-	*47.90 FL
36	1		*REAR TAILGATE WORDING PRIUS	Necessary	54.60 FL	-	*54.60 FL
37	1		*REAR TAILGATE WORDING HYBRID	Necessary	54.60 FL	-	*54.60 FL
38	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	-	*- FL
39	1		*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	-	*- FL
40	1		*SET PARKING AID	Dented	700.00 FS	-	*220.00 FS
41	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	-	*60.00 FS
42	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	-	*80.00 FS
43	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	-	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
44	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	-	*30.00 FS
45	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
46	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
47	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	-	*- FS
48	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*- FS
49	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	-	*- FS
50	1		*SET TAILLAMP LOWER CLIP	Not Necessary	55.00 FS	-	*- FS
51	1		*SET TAILLAMP UPPER CLIP	Necessary	55.00 FS	-	*55.00 FS
52	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	-	*- FS
53	1		*REAR SPOILER CLIP	Not Necessary	70.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,018.40	5,544.00
- List Item Discount on L Items 25.00/25.00% (\$)	3,483.35	1,209.75
Total Parts (\$)	12,535.05	4,334.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	180.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	600.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	880.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			8,920.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >