

Not Authorized
1/1/2022

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD5483R

AAD2204-

Vehicle No.:
 Chassis No.:
 Co UEN:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

28 APR 2022

SHD5483R
 JTDKB3FU603079185
 200303878K
 TOYOTA
 PRIUS
 26/04/2022
SLN6840L/TOKIO
 25/01/2019

PART	LIST	Price	Status
1 COVER, REAR BUMPER	\$ B1	442.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ B1	332.70	✓
1 COVER, REAR BUMPER, LOWER	\$ mis	15.40	✓
1 GUARD, REAR BUMPER, CENTER	\$ B1	576.30	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ my car	116.50	✓
1 RETAINER, REAR BUMPER SIDE, RH	\$ su	117.70	X
1 FILLER, REAR BUMPER EXTENSION, RH	\$ su	123.70	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$ su	123.70	X
1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$ CM	443.30	✓
1 LENS AND BODY, REAR LAMP, LH (LOWER)	\$ su	502.00	X
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$ CM	451.80	✓
1 LENS AND BODY, REAR LAMP, RH (LOWER)	\$ su	502.00	X
1 BOX, DECK FLOOR, RH	\$ su	313.60	X
1 BOX, DECK FLOOR, LH	\$ su	313.00	X
1 BOX, DECK FLOOR, REAR	\$ su	105.80	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	175.10	?
1 COVER, FLOOR UNDER, NO.2 RH	\$	241.90	?
1 COVER, REAR FLOOR CTR	\$ mis	229.90	✓
1 COVER, DECK TRIM, REAR	\$ su	126.70	X
1 PAN, REAR FLOOR	\$ R	583.40	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	?
1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$ R	467.00	X
1 SWITCH ASSY, BACK DOOR OPENER	\$ su	179.10	X
1 SPOILER, SUB ASSY, REAR	\$ su	1,575.40	X
1 PANEL SUB-ASSY, BACK DOOR	\$ B1	1,147.80	✓
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ CM	925.60	✓
1 BOARD ASSY, BACK DOOR TRIM	\$ su	259.20	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-

SHDS483R

1 WEATHERSTRIP, BACK DOOR	\$	Pr	372.30 X
1 BOARD, BACK DOOR TRIM	\$	Pr	225.20 X
1 BOARD, REAR FLOOR, NO.1	\$	Pr	519.00 X
1 STAY ASSY, BACK DOOR, LH	\$	Pr	242.50 X
1 STAY ASSY, BACK DOOR, RH	\$	Pr	242.50 X
1 HINGE ASSY, BACK DOOR, LH	\$	R	61.00 X
1 HINGE ASSY, BACK DOOR, RH	\$	R	61.00 X
1 REAR TAILGATE TOYOTA LOGO	\$	Pr	47.90 ✓
1 REAR TAILGATE WORDING 'PRIUS'	\$	Pr	54.60 ✓
1 REAR TAILGATE WORDING 'HYBRID'	\$	Pr	54.60 ✓
1 PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50 X
1 LINER, REAR WHEEL HOUSE, RH	\$	Pr	139.80 X

TOTAL	\$	12,922.10
25%	\$	3,230.53
	\$	9,691.58

Special Nett

1SET PARKING AID	\$	Net	700.00	2205M
1SET REAR BUMPER CLIP	\$	Pr	95.00	605M
2 WINDSCREEN SEALANT	\$	Pr	150.00	805M
1 WINDSCREEN MOULDING	\$	Pr	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	Pr	130.00	305M
1 REAR TAILGATE STICKER "Trans-Cab"	\$	Pr	80.00	305M
1 REAR TAILGATE STICKER "6555-3333"	\$	Pr	80.00	305M
1 REAR BUMPER PROTECTOR	\$	NSP	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	Pr	85.00	X
1 REAR NUMBER PLATE WITH HOLDER	\$	Pr	140.00	X
1SET TAILLAMP LOWER CLIP	\$	Pr	55.00	X
1SET TAILLAMP UPPER CLIP	\$	Pr	55.00	✓
1 END PANEL TRIM CLIP	\$	Pr	65.00	X
1 REAR SPOILER CLIP	\$	Pr	70.00	X

TOTAL	\$	2,085.00
--------------	-----------	-----------------

TOTAL PARTS	\$	11,776.58
--------------------	-----------	------------------

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-

SHD5483R

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	180l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	600l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	60l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	?
Towing Fees	\$	nn 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	880l
To reinstall rear bumper parking sensor.	\$	170.00	50l
To Check Electrical Lighting Concerned.	\$	170.00	20l

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5483R

To transfer of luggage floor panel fittings, attachment and perform water seepage test. \$ *na* 380.00 X

To transfer of tire, rim and on wheel balancing. \$ *na* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. \$ *na* 380.00 X

TOTAL \$ 8,920.00

Over All Total \$ 20,696.58

(PART-BY-PART) Repair Days *25 DAYS*
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: