

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

not Authorized
 here
 29/4/22
 2/5 \$ 11,200 /
 10 days

VEHICLE No: SGZ 1805T

1PC	BOOTLID	Bent/Bull	621.10	\$966.10	/
1PC	BOOTLID REAR LOGO	neu		\$68.50	/
1PC	BOOTLID 'VIOS' EMBLEM	neu	52.00	\$62.80	/
1PC	BOOTLID 'G' EMBLEM	neu	50.00	\$58.00	/
1PC	BOOTLID INNER LOCK	twl	145.50	\$409.10	/
1PC	BOOTLID LOCK STRICKER	11		\$66.80	X
1PC	BOOTLID WEATHERSTRIP	twl	166.10	\$282.30	/
1PC	BOOTLID OUTER CHROME GARNISH	11		\$621.80	X
1PC	BOOTLID INNER TRIM	11		\$366.10	X
2PCS	BOOTLID HINGES @\$165.00	R		\$330.00	X
1PC	REAR BUMPER	Dis	381.10	\$655.10	/
2PCS	REAR BUMPER BRACKETS @\$80.00	Bent		\$160.00	/
2PCS	REAR BUMPER REFLECTORS @\$60.00	one		\$120.00	/
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	Bent		\$130.00	/
1SET	REAR BUMPER CLIPS	neu		\$50.00	/
1PC	REAR END PANEL	Body	580.20	\$788.20	/
1PC	REAR END PANEL TOP GARNISH	twl	166.80	\$362.30	/
2PCS	TAILLAMPS @\$680.00	one	355.10 x 2 = 710.20	\$1,360.00	/
2PCS	TAILLAMP LOWER BRACKETS @\$65.00	one	45 x 2 = 90	\$130.00	/
2PCS	TAILLAMP HOUSING PANELS @\$425.00	R		\$850.00	X
1PC	REAR FLOOR PANEL	R		\$1,145.20	X
1PC	REAR FLOOR PANEL TOP BOARD	Torn	245.10	\$620.50	/
2PCS	REAR FLOOR PANEL TOOLS SPONGE @\$280.00	Torn	254 x 2 = 508	\$560.00	/
2PCS	REAR FENDERS @\$945.10	R		\$1,890.20	X
2PCS	REAR FENDER INNER TRIMS @\$281.10	11		\$562.20	X
1PC	REAR FENDER UNDER SHIELD N/S	Torn		\$48.00	/
1PC	REAR EXHAUST	R		\$899.10	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$122.10	X
1PC	REAR EXHAUST MOUNTING	11		\$45.00	X
1PC	REAR SPARE TYRE LOCK NUT	11		\$55.10	X
1PC	REAR WINDSCREEN	11		\$1,085.20	X
1PC	REAR WINDSCREEN MOULDING	11		\$118.00	X
1PC	BONNET	Bent/worped	982.20	\$1,426.10	/
1PC	BONNET INNER RUBBER	neu		\$45.00	/
2PCS	BONNET HINGES @\$115.00	11		\$230.00	X
1PC	BONNET INSULATOR	11		\$281.00	X
1PC	BONNET LOCK	twl		\$105.00	/
1PC	FRONT BUMPER	Dis	408.10	\$681.10	/
2PCS	FRONT BUMPER SIDE RETAINERS @\$45.00	Bent		\$90.00	/
1PC	FRONT BUMPER INNER TOP RETAINER	Dis	231.10	\$350.00	/
1PC	FRONT BUMPER CENTRE GRILLE	Torn	86.20	\$108.00	/
1PC	FRONT BUMPER BEAM	Bent	391.20	\$561.10	/

2PCS	FRONT BUMPER BEAM BRACKETS @190.00	but		\$380.00	/
2PCS	FRONT BUMPER FOG LAMPS @\$361.00	misc	295.50	\$722.00	1pc
2PCS	FRONT BUMPER FOG LAMP COVERS @\$105.00	11		\$210.00	X
1SET	FRONT BUMPER CLIPS	del		\$50.00	/
1PC	FRONT WIPER WASHER TANK	re		\$188.00	/
1PC	FRONT GRILLE	one		\$381.90	/
1PC	FRONT GRILLE LOGO	new		\$68.50	/
2PCS	HEADLAMPS @\$ 850.00	holder one	1132.20	\$1,700.00	/
1PC	FRONT BRACE PANEL	NS		\$121.00	X
2PCS	FRONT FENDERS @\$761.00	R		\$1,522.00	X
2PCS	FRONT FENDER INNER SHIELDS @\$161.00	11		\$322.00	X
2PCS	FRONT FENDER 'VVTI' EMBLEMS @\$58.00	11		\$116.00	X
1PC	FRONT SUPPORT PANEL	but	745.20	\$1,160.00	/
1PC	FRONT SUPPORT PANEL TOP GARNISH	NF		\$210.00	X
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	NN		\$50.00	X
1PC	AIR CON CONDENSER	but/pun	1018.20	\$1,813.10	/
1PC	AIR CON DISCHARGE HOSE	11		\$481.90	X
1PC	AIR CON SUCTION HOSE	11		\$455.10	X
1PC	AIR CON PIPE	11		\$211.00	X
1PC	AIR CLEANER BOX ASSY	11		\$650.00	X
1PC	RADIATOR	but/pun	1180.20	\$2,101.10	/
1PC	RADIATOR FAN ASSY	JM	257 745.50	\$850.00	/
				\$32,628.60	

S.NETT ITEM

1PC	REAR WINDSCREEN SEALANT	11		\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11		\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	shorted		\$280.00	200
1PC	REAR END PANEL SEALANT	new		\$50.00	/
1SET	REAR FLOOR PANEL INSULATOR	11		\$250.00	X
1SET	REAR REVERSE CAMERA	11		\$380.00	X
1PC	REAR LICENCE PLATE	11		\$50.00	X
1PC	FRONT LICENCE PLATE	one		\$50.00	40
1BOL	RADIATOR COOLANT	del		\$40.00	30

	TO CHECK WIRING			\$50.00	30
	TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN	11		\$120.00	X
	TO DISMANTLE & REFIX REAR EXHAUST			\$100.00	60
	TO DISMANTLE & REFIX FUEL TANK	11		\$100.00	X
	TO DISMANTLE & REFIX BOOTLID MECHANISM			\$100.00	60
	TO RESET & REPROGRAMME SYSTEM			\$100.00	50
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$120.00	80
	TO CONDUCT WHEEL ALIGNMENT	11		\$100.00	X
	TO REFILL AIR CON GAS			\$100.00	/
	TO SPRAY RUST PROOFING			\$200.00	120
	LABOUR FOR PANEL BEATING & REPLACED PARTS			\$4,500.00	1800

TO PUTTY & SPRAY PAINTING

TOTAL \$2,800.00 1800
\$42,298.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1281660
254
P-961245
S.N-320
L-4150
1408244
292
11265