

LLDR

bec / Mark

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-09, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SJU 8371Y

Made : Toyota

Model : Vios

Chassis No :

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bootlid	1	\$ 625.00	\$ 625.00
2	Rear Bootlid "E" Emblem	1	\$ 51.10	\$ 51.10
3	Rear Bootlid "Vios" Emblem	1	\$ 51.10	\$ 51.10
4	Rear Bootlid Emblem	1	\$ 53.90	\$ 53.90
5	Rear Bootlid Hinge RH	1	\$ 182.25	\$ 182.25
6	Rear Bootlid Hinge LH	1	\$ 182.25	\$ 182.25
7	Rear Bootlid Lock	1	\$ 381.90	\$ 381.90
8	Rear Bootlid Lock Striker	1	\$ 43.55	\$ 43.55
9	Rear Bootlid Outer Garnish	1	\$ 281.70	\$ 281.70
10	Rear Bootlid Weatherstrip	1	\$ 185.10	\$ 185.10
11	Rear Bumper	1	\$ 474.80	\$ 474.80
12	Rear Bumper Side Retainer RH	1	\$ 98.40	\$ 98.40
13	Rear Bumper Side Retainer LH	1	\$ 98.40	\$ 98.40
14	Rear Bumper Bracket RH	1	\$ 131.35	\$ 131.35
15	Rear Bumper Bracket LH	1	\$ 131.35	\$ 131.35
16	Rear Bumper Reflector RH	1	\$ 87.60	\$ 87.60
17	Rear Bumper Reflector LH	1	\$ 87.60	\$ 87.60
18	Rear Bumper Support Bracket RH	1	\$ 33.20	\$ 33.20
19	Rear Bumper Support Bracket LH	1	\$ 33.20	\$ 33.20
20	Rear Taillamp Assembly RH	1	\$ 409.60	\$ 409.60
21	Rear Taillamp Assembly LH	1	\$ 409.60	\$ 409.60
22	Rear End Panel	1	\$ 682.10	\$ 682.10
23	Rear End Panel Top Garnish	1	\$ 211.10	\$ 211.10
24	Rear Spare Tyre Panel Top Board	1	\$ 172.10	\$ 172.10
25	Rear Spare Tyre Panel Side Sponge RH	1	\$ 287.00	\$ 287.00
26	Rear Spare Tyre Panel Side Sponge LH	1	\$ 377.25	\$ 377.25
27	Rear Spare Tyre Panel Centre Sponge	1	\$ 378.20	\$ 378.20
28	Rear Spare Tyre Panel	1	\$ 673.20	\$ 673.20
29	Rear Floor Side Extension Panel RH	1	\$ 134.70	\$ 134.70
30	Rear Floor Side Extension Panel LH	1	\$ 134.70	\$ 134.70
31	Rear Fender RH	1	\$ 989.00	\$ 989.00
32	Rear Taillamp Panel RH	1	\$ 231.20	\$ 231.20

BT ✓

NEC ✓

NDX

NDX

CUT ✓

NEC ✓

NSX

BR ✓

NDX

NSX

BR ✓

NDX

NDX

NDX

NDX

NDX

NDX

NDX

PD ✓

BT ✓

33	Rear Fender Inner Trim RH	1	\$	224.10	\$	224.10	NDX
34	Rear Fender Inner Shield RH	1	\$	175.00	\$	✓ 175.00	BR ✓
35	Rear Fender Air Duct RH	1	\$	131.70	\$	131.70	
36	Rear Shock Absorber RH	1	\$	290.00	\$	290.00	
37	Rear Wheel Hub with Bearing RH	1	\$	550.00	\$	550.00	ND
38	Rear Axle	1	\$	2,850.00	\$	2,850.00	X
Parts Sub Total :					\$	12,524.30	
3345.10 -25% 2508.82					Discount	\$	3,131.08
25%					PARTS TOTAL :	\$	9,393.23

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ 50.00	NNX
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30.00 ✓ 50.00	NECV
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ 50.00	} NNX
4	Rear Fender Inner Trim Clips - Set	1	\$ 40.00	\$ 40.00	
5	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00	
6	Rear Fender Inner Shield Clips - Set	1	\$ 20.00	\$ ✓ 20.00	NECV
7	Rear Bootlid Sealant	1	\$ 150.00	\$ 150.00	} NNX
8	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00	
9	Rear Spare Tyre Panel Sealant	1	\$ 150.00	\$ 150.00	
10	Rear Fender Sealant	1	\$ 150.00	\$ 150.00	
11	Rear Windscreen Glass Sealant	1	\$ 120.00	\$ 120.00	
12	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 250.00	
13	Rear Wheel Rim RH	1	\$ 300.00	\$ 300.00	
SPECIAL NETT TOTAL :				\$ 2,030.00	

50

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 800.00 1,800.00
2	To Spray Paint Affected Areas	\$ 600.00 1,600.00
3	Wiring & Bulb Check	\$ 100.00 100.00
4	To Remove & Refix Rear Windscreen Glass	\$ 120.00 150.00
5	To Transfer Rear Bootlid Mechanism	\$ 80.00 150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 60.00 120.00
7	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ 150.00 150.00
8	To apply anti rust on affected parts	\$ 120.00 120.00
9	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00 150.00
10	To Remove & Refix Rear Undercarriage	\$ 350.00 350.00
11	To Conduct Four Wheel Alignment	\$ 150.00 150.00
12	To Conduct Water Leak Test	\$ 100.00 100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00 480.00
		LABOUR TOTAL : \$ 5,420.00

1660

Survey + Resurvey

1415 hrs

Totum hui

4218.82

L/S - 3375.05
= 3400

Lump sum repair

Repair days 7

PARTS TOTAL : \$ 9,393.23
SPECIAL NETT TOTAL : \$ 2,030.00
LABOUR TOTAL : \$ 5,420.00
GRAND TOTAL : \$ 16,843.23

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: