Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Pauline Tham Date: 22 May 2023

Preliminary Advice

Insured Vehicle No : GX7546L

TP Vehicle No : SJU8371Y Accident Date : 27/04/2022 Make : TOYOTA VIOS Assignment Date : 09/05/2022

Date of Inspection : 29/04/2022 Est. Duration of Repair : 7

Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)

8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,843.23
Revised Amount	:S\$	4,218.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,218.83
Lump Sum Repair	·S\$	3 400 00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

cle is uneconomical					

⁽ X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.