



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004038/Evy3m4	
			Date: 08/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 4212U	Veh. Inspected	GBL 7119J
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001039MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	29/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	BYD T3	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	LC0CE4DB4M0090136	Colour	ORANGE
	Odometer	1247 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/R15C	DUNLOP	4 mm
	L/H Front Tyre	185/R15C	DUNLOP	4 mm
	R/H Rear Tyre	185/R15C	DUNLOP	4 mm
	L/H Rear Tyre	185/R15C	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/04/2022	Inspection Date	29/04/2022
	Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	