

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22004039/EGA3Q2**Date:** 07/07/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000102\_03

**Claimant Vehicle No :** SKU4188A **Insured Vehicle No :** PC5764R

Date of Loss: 28/04/2022 Nature of Claim: TP Claim No: MFL2022D0002181

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKU4188A**

Make & Model: MERCEDES-BENZ E200, 2.0 SEDAN (R17) (A) Engine No: 27492030356030

Reg. Date: 26/06/2015 (Man. Year: 2015) Chassis No: WDD2120342B144030

Colour: Red Odometer: 125452 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 1,500.00          | 650.00            | 850.00            | 56.67         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                         | <b>1,500.00</b>   | <b>650.00</b>     | <b>850.00</b>     | <b>56.67</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 105.00            | 45.50             | 59.50             | 56.67         |
| <b>Nett Amount (S\$)</b>                         | <b>1,605.00</b>   | <b>695.50</b>     | <b>909.50</b>     | <b>56.67</b>  |
| <b>+ Loss of Use (2.0 x S\$100.00/day) (S\$)</b> |                   | 200.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>902.95</b>     |                   |               |

**INSPECTION**

Date of Assignment: 29/04/2022

Date Inspected: 05/05/2022 Inspected At: Connect 3 ( WOODLANDS) (HQ)  
566 Woodlands Road (Mandai Estate)  
Singapore 728697

Estimated Period of Repair: 2.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |  |
|---------------|--|--|
| Reference     |  |  |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 22 Jun 2022)                            |
| Parts:        | 143  | MERCEDES-BENZ E200 2.0 SEDAN (R17) (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)  |
| Print Code:   | (Unsubmitted, no print-code for SKU4188A)  |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars    | Lab.Type | Repairer's      | Amount        |
|--------------------------------|----------------|----------|-----------------|---------------|
| <b>Labour Items</b>            |                |          |                 |               |
| 1                              | LABOUR CHARGES | New      | 600.00          | 250.00        |
| 2                              | SPRAY PAINTING | New      | 900.00          | 400.00        |
| <b>Gross Labour Cost (S\$)</b> |                |          | <b>1,500.00</b> | <b>650.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >