

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP21120022

Date: 31 MAR 2022

**Mohd Aziz Bin Mohd Salleh**  
**c/o Eng Soon Painting SVC**  
**Blk 4 Yew Tee Ind Est 393 - J**  
**Woodlands Road**  
**Singapore 677969**

## THIRD PARTY SURVEY ACCIDENT OCCURED ON 09 DEC 2021

Workshop Name and Address

Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

As per your instruction dated 10 DEC 2021  
We have carried out a physical inspection on the said  
We enclosed herewith our report and findings as follows:

with regard to the above matter.  
SLG6770S

### 1. VEHICLE PARTICULARS

Registration No : SLG6770S

Engine No : 1AZE114207

Model : TOYOTA CAMRY 2.0

Mileage : N.A km

Year / Capacity : Sep 2008 / 1998 cc

Colour : Metallic Black

Chassis No : MR053BK4107034438

### 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Sport
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Sport
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Sport

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 10 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLG6770S

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front bumper X SVC	bent	\$ 650.00	\$ 650.00
1 pc	Front bumper side retainer X SVC	bent	\$ 65.00	\$ 65.00
1 pc	Front bumper reinforcement X SVC	bent	\$ 350.00	\$ 350.00
10 pcs	Front bumper clips ✓	necessary	\$ 80.00	\$ 30(SN) 80.00
1 pc	Headlamp assembly ✓	grazed/deformed	\$ 845.00	\$ 713.8 845.00
1 pc	Headlamp clips X SVC	necessary	\$ 15.00	\$ 15.00
1 pc	Front fender X Repair	bent	\$ 525.00	\$ 525.00
1 pc	Front fender splash shield X SVC	deformed	\$ 150.40	\$ 150.40
10 pcs	Front fender splash shield clips X SVC	necessary	\$ 80.00	\$ 80.00
1 pc	Front door assembly X Repair	bent	\$ 1,050.00	\$ 1,050.00
1 pc	Front door weatherstrip X SVC	bent	\$ 165.00	\$ 165.00
1 pc	Front door outer protector ✓	grazed/deformed	\$ 115.00	\$ ✓ 115.00
8 pcs	Front door outer protector clips X SVC	necessary	\$ 80.00	\$ 80.00
1 pc	Front knuckle arm X SVC	bent	\$ 381.50	\$ 381.50
1 pc	Front lower arm X SVC	bent	\$ 120.50	\$ 120.50
1 pc	Front absorber X SVC	bent	\$ 425.00	\$ 425.00
1 pc	Front wheel bearing hup X SVC	bent	\$ 180.50	\$ 180.50
1 pc	Front link rod assy X SVC	distorted	\$ 88.90	\$ 88.90
1 pc	Rear door assembly X Repair	bent	\$ 1,250.00	\$ 1,250.00
1 pc	Rear door outer protector ✓	grazed/deformed	\$ 105.00	\$ ✓ 105.00
8 pcs	Rear door outer protector clips X SVC	necessary	\$ 64.00	\$ 64.00
1 pc	Rear door weatherstrip X SVC	bent	\$ 150.00	\$ 150.00
1 pc	Rocker panel garnish X SVC	deformed	\$ 450.00	\$ 450.00
10 pcs	Rocker panel garnish clips X SVC	necessary	\$ 80.00	\$ 80.00
1 pc	Rear lower arm X SVC	bent	\$ 250.00	\$ 250.00
1 pc	Rear upper arm X SVC	bent	\$ 280.00	\$ 280.00
1 pc	Rear control arm X SVC	bent/distorted	\$ 180.00	\$ 180.00
1 pc	Rear cross member X SVC	bent/distorted	\$ 750.00	\$ 750.00
1 pc	Rear wheel bearing hup X SVC	distorted	\$ 125.00	\$ 125.00
1 pc	Rear anti roll bar link X SVC	bent/distorted	\$ 80.00	\$ 80.00
1 pc	Rear shock absorber X SVC	distorted	\$ 220.00	\$ 220.00
1 pc	Side mirror housing assy X SVC	grazed/deformed	\$ 579.80	\$ 579.80

Vehicle Number : SLG6770S

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Rear fender ✓	bend/distorted	\$ 725.00	\$ ✓ 725.00
1 pc	Rear bumper ✓	bent	\$ 650.00	\$ 561.8 650.00
1 pc	Rear bumper side retainer ✓	bent	\$ 50.00	\$ ✓ 50.00
1 pc	Rear bumper side bracket X SVC	bent	\$ 65.00	\$ 65.00
1 pc	Rear bumper lower bracket X SVC	bent	\$ 85.00	\$ 85.00
10 pcs	Rear bumper clips ✓	necessary	\$ 80.00	\$ 30(SN) 80.00
1 pc	Tail lamp assy ✓	distorted	\$ 425.00	\$ ✓ 425.00
1 pc	Tail lamp sealant X SVC	necessary	\$ 50.00	\$ 50.00
2 pcs	Tail lamp clips X SVC	necessary	\$ 40.00	\$ 40.00
1 pc	Tail lamp base panel X Repair	dent/distorted	\$ 362.40	\$ 362.40
Parts Sub-Total			\$ 12,463.00	\$ 2695.6 12,463.00
Discount 25.00%			\$ 3,115.75	\$ 3,115.75
			\$ 9,347.25	\$ 2021.7 9,347.25

Vehicle Number : SLG6770S

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 pc	wheel rim assy ( sport ) ✓	damaged	\$ 600.00	\$ 400 600.00
1 pc	Tyre ✓	grazed	\$ 450.00	\$ 100 400.00
Special Nett Sub-Total			\$ 1,050.00	\$ 1,000.00
Spare Parts Total			\$ 13,513.00	\$ 13,463.00

**LABOUR COST**

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
	Spare Parts Total c/f	\$ 13,513.00	\$ 13,463.00
1	Towing	\$ 120.00	\$ 50 120.00
2	To check and reconnect snap wiring	\$ 180.00	\$ 30 150.00
3	To tuff coat affected areas	\$ 180.00	\$ 60 150.00
4	To remove and transfer front and rear door mechanism	\$ 200.00	\$ X 180.00
5	To respray affected areas	\$ 1,600.00	\$ 1200 1,400.00
6	To remove and refix interior upholstery	\$ 180.00	\$ 60 150.00
7	To renew damaged parts, straighten and repair door center pillar (inner), front door pillar, rear fender, rocker panel and aligned all parts.	\$ 1,800.00	\$ 800 1,600.00
8	To dismantle/replace all suspension and undercarriage parts.	\$ 280.00	\$ X 250.00
9	To press out and in wheel bearing	\$ 180.00	\$ X 150.00
10	To conduct wheel alignment.( Before & After )	\$ 180.00	\$ 60 150.00
			2260
	Total	\$ 18,413.00	\$ 17,763.00


The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 14,000.00

4781.7

-20%: 3800

8 Days



Fong Kok Heng  
Qualified Appraiser

