

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 28.04.22

3P INSURANCE:

NTUC

MODEL: HYUNDAI I40

SURVEYOR:

LKK

VEH NO.: SHD6824J

MVA:

LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$553.00 ✓
	Rear Bumper Reinforcement	1		\$428.40 2 an
	Rear Bumper Stay LH	1		\$80.30 7 an
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 ✓
	Rear Bumper Side Bracket LH	1		\$35.60 2 an
	Rear Bumper Sponge	1		\$119.50 2 an
	Rear Bumper Under Cover	1		\$228.00 ✓
	Rear Bumper Reflector LH	1		\$32.00 ✓
	Exhaust Muffler LH	1		\$967.70 ✓
	Exhaust Pipe Centre	1		\$730.10 2 ✓
SPARE PARTS SUB TOTAL				\$ 3,196.60 2532.80
LESS 20%				\$ 639.32 2026.24
DISCOUNTED SPARE PARTS TOTAL				\$ 2,557.28
	Reverse Sensors	1		\$ 135.70 ✓
SUB NETT				\$ 135.70
LESS 10%				\$ 13.57
NETT TOTAL				\$ 122.13 ✓
	Rear Fender Adv.Sticker RH / LH	2	\$ 100.00	\$ 200.00 S/NETT ✓
	Rear Bumper Adv.Sticker	1		\$ 50.00 S/NETT ✓
SPARE PARTS & OTHERS TOTAL				\$ 2,929.41 250
	Panel Beating			\$ 300.00 280
	Spray Painting Charge			\$ 300.00 250
	Remove/Refix Reverse Sensor			\$ 120.00 30
	Remove/Refix Exhaust Pipe			\$ 120.00 60 620
	VEHICLE TOWING FEE			- x an
LABOUR TOTAL				\$ 840.00 3018.37
ESTIMATE TOTAL				\$ 3,769.41 4591.50

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tanfai 97427749
 - WP 28/4/22 e sm
 15 days after repair
 02 days
 tanfai @ Phantom