

COMFORT TRANSPORTATION PTF LTD

REPAIR ESTIMATE

Vehicle No. : SHA8707S

Date: 28/04/2022

Make : Toyota

Insurance: NTUC

Model : Prius

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$ 503.04
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 55.80
1	REAR BUMPER UNDER SIDE EXTENTION RH			\$ 148.40
1	REAR BUMPER LOWER COVER			\$ 654.96
1	REAR BUMPER TOWING COVER			\$ 82.70
1	REAR FENDER RH			\$ 992.04
1	TAIL LAMP RH LOWER			\$ 570.00
1	TAIL LAMP RH UPPER			\$ 557.90
1	REAR BUMPER SIDE RETAINER RH			\$ 94.80
1	REAR BUMPER REINFORCEMENT			\$ 378.32
1	BACK DOOR GARNISH SUB ASSY			\$ 1,054.71
1	REAR TRUNK LID LOGO (PRIUS)			\$ 62.14
1	REAR TRUNK LID LOGO (HYBRID)			\$ 62.14
	SUB TOTAL		1956.98	\$ 5,238.95
	LESS 25%		1467.73	\$ 1,309.74
	DISCOUNTED TOTAL			\$ 3,929.21
	REAR TRUNK LID COMFORT & TEL NO. STICKER		-10%	\$ 60.00
	REAR TRUNK LID APPS STICKER		-10%	\$ 40.00
	REAR BUMPER REVERSE SENSOR		-10%	\$ 135.70
	REAR BUMPER RUBBER MAT			\$ 50.00
				\$ 285.70
	Labour Charge			
	PANEL BEATING			\$ 800.00
	SPRAY PAINTING CHARGE			\$ 600.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	CHECK ALL LIGHTING			\$ 80.00
	TUFF KOTE			\$ 50.00
	TOTAL LABOUR		1085	\$ 1,590.00
	ESTIMATE TOTAL		4582.50	\$ 5,804.91

am
de
Xnh
Ry
de
Xnh
Xnh
Ry
am
Xnh
Ry
am
am
Nett
Nett
Nett
Nett
525
500
30
30
Xnh

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495747
w/ 28/4/22 05pm
4/9 Posny after repair
tanji@lkkauto.com
23 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer