3/30/23, 12:27 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22004050/KNY3Q2

Singapore 079909 **Date:** 30/03/2023

REFERENCE

Insured/Claimant: KONTOURZ PTE LTD Policy No: DMCVSNA00118172102

Date of Loss: 21/04/2022 Nature of Claim: OD Claim No: SNM22D202705/C01/TANKW/CHEESC

Engine No:

Chassis No:

Odometer:

4P10D26150

102483 km

FFA01BA30056

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ4042B

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEK

(CBU) (M)

Reg. Date: 15/04/2019 (Man. Year: 2018)

Colour: White

Engine Capacity: 2998 cc Market Value/New Car Price: \$\$63,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8 (D)
Front Left Side: Arivo 8 mm Rear Left Side: Arivo 9/9 mm
Front Right Side: Arivo 8 mm Rear Right Side: Arivo 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		13,967.00	10,817.60	3,149.40	22.55
Miscellaneous Items		58.00	58.00	0.00	0.00
Labour		3,433.25	3,147.52	285.73	8.32
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	17,458.25	14,023.12	3,435.13	19.68
	- Excess (S\$)	0.00	600.00	-600.00	
	(S\$)	17,458.25	13,423.12	4,035.13	23.11
	+ GST 7.00/8.00% (S\$)	1,222.08	1,073.85	148.23	12.13
	Nett Amount (S\$)	18,680.33	14,496.97	4,183.36	22.39

INSPECTION

Date of Assignment: 29/04/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 29/04/2022 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Mar 2023)

Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR1SDEK (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ4042B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		12,929.00 F	*12,484.00 FL
<u>Sup</u>	<u>pleme</u>	entary #1				
2	1		*COOLING COIL PIPE	Dented	78.00 F	*78.00 FL
3	1		*FRAME CROSSMEMBER	Bent	280.00 F	*280.00 FL
4	1		*L/F MUD PANEL	Bent	75.00 F	*75.00 FL
5	1		*R/INSTR PANEL COVER	Cracked	245.00 F	*245.00 FL
6	1		*RH BUMPER STAY	Bent	70.00 F	*70.00 FL
7	1		*CROSSBAR SHAFT BRKT	Bent	290.00 F	*290.00 FL
F=Fra	anchise	part. L=ListItem	Disc.			,
				Sub Total (S\$)	13,967.00	13,522.00
			- List Item Discount on	L Items 0.00/20.00% (S\$)	0.00	2,704.40
				Total Parts (S\$)	13,967.00	10,817.60

Report was unsubmitted during this print-out.

Gross Labour Cost (S\$)

3,433.25

3,147.52

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRAS		58.00	58.00
	Sub Total (S\$)	58.00	58.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 LABOUR	New	2,402.40	2,171.40
2 SPRAY PAINTING	New	1,030.85	976.12

Report was unsubmitted during this print-out.

< END OF ESTIMATES >