### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Attn: Billy Tan 29 Mar 2023 Date:

## **Preliminary Advice**

Vehicle No : GBJ4042B **Accident Date** : 21/04/2022

: MITSUBISHI CANTER Make Policy No.

DMCVSNA00118172102

**Assignment Date** : 29/04/2022 : S\$600.00 **Excess** Est. Duration of Repair Date of Inspection : 29/04/2022 : 12

: CHENG HOE MOTOR PTE LTD (YISHUN) Inspection At

BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A

SINGAPORE 768761

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,458.25 (inclusive supp \$1038.00)
-----------------------------	------	--------------------------------------

**Revised Amount** :S\$ 14,023.12 Check Items (Estimated) :S\$ 0.00 Total :S\$ 14,023.12

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 63,000.00 COE / PARF Rebate :S\$ 18,859.00

Salvage Value :S\$

Margin for Repair :S\$ 44,141.00

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Ki	indly
		let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approve on supplementary