



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS3/AWA21012941/Tqy3e2-1	Date: 06/06/2022
			Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YM 4085P	Veh. Inspected	SG 5515L
	Policy No.	BVFCB0013662102	Coverage (\$)	0.00
	Claim No.	NSV2100163/HLF	Excess (\$)	0.00
	Assign From	HEW LEE FONG	Assign Date	29/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO B9TL	c.c	9364
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	YV3S4P925HA183185	Colour	GREEN
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/12/2021	Inspection Date	21/12/2021
	Survey held at	SBS TRANSIT LTD (Branch) 4 DEFU LANE 1 SINGAPORE 539536		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	