

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |                          |                  |       |                         |  |
|------------------------------------|---|--------------------------|------------------|-------|-------------------------|--|
|                                    | ALLIED WORLD A  | SSURANCE COMPANY LTD     |                  | Ref:  | CS3/AWA21012941/Tqf3e2  |  |
|                                    | (SINGAPORE BRA<br>(8th FLOOR) MAPI<br>SINGAPORE 0799  |                          |                  | Date: | 27/04/2022              |  |
|                                    |   |                          | 1                | Code: | AWA                     |  |
| 1.                                 | Policy Particulars :- (THIRD PARTY CLAIM)   |                          |                  |       |                         |  |
|                                    | Insured Veh.  | YM 4085P                 | Veh. Inspected   |       | SG 5515L                |  |
|                                    | Policy No.  | BVFCSB0013662102         | Coverage (\$)    |       | 0.00                    |  |
|                                    | Claim No.   | NSV2100163/HLF           | Excess (\$)      |       | 0.00                    |  |
|                                    | Assign From   | HEW LEE FONG             | Assign Date      |       | 21/12/2021              |  |
| 2. Vehicle Particulars & Condition |   |                          |                  |       |                         |  |
|                                    | Make & Model  | VOLVO B9TL               | c.c              |       | 9364                    |  |
|                                    | Engine No.  | HIDDEN                   | Year of Reg.     |       | 2017                    |  |
|                                    | Chassis No.   | YV3S4P925HA183185        | Colour           |       | GREEN                   |  |
|                                    | Odometer  | -                        | Steering         |       | IN ORDER                |  |
|                                    | Brakes  | IN ORDER                 | Modification     |       | NIL                     |  |
|                                    | General   | GOOD                     |                  |       |                         |  |
| 3. Conditions of Tyres             |   |                          |                  |       |                         |  |
|                                    |   | Size                     | Make             |       | Balance                 |  |
|                                    | R/H Front Tyre  | 275/70 R22.5             | BRIDGESTONE      |       | 8 mm                    |  |
|                                    | L/H Front Tyre  | 275/70 R22.5             | BRIDGESTONE      |       | 8 mm                    |  |
|                                    | R/H Rear Tyre   | 275/70 R22.5 (D)         | BRIDGESTONE      |       | 8/8 mm                  |  |
|                                    | L/H Rear Tyre   | 275/70 R22.5 (D)         | BRIDGESTONE      |       | 8/8 mm                  |  |
| 4.                                 | Description of Damages  |                          |                  |       |                         |  |
|                                    | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |                          |                  |       |                         |  |
| 5.                                 | General Information   |                          |                  |       |                         |  |
|                                    | Accident Date   | 06/12/2021               | Inspect Date / T | ime   | 21/12/2021 ( 04:30 PM ) |  |
|                                    | Survey held at  | SBS TRANSIT LTD (Branch) | •                |       |                         |  |
|                                    | 4 DEFU LANE 1 SINGAPORE 539536  |                          |                  |       |                         |  |
| 5a.                                | Remarks   |                          |                  |       |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000 |                          |                  |       |                         |  |
| 5b.                                | Estimate Days of Repair   |                          |                  |       |                         |  |
|                                    | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days  |                          |                  |       |                         |  |
|                                    | Report Ref No. CS3/AWA21012941/Tqf3e2   |                          |                  |       |                         |  |

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser