

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Vimmala

Date: 06 May 2022

Preliminary Advice

Vehicle No	: YP3896G	Accident Date	: 28/04/2022
Make	: MITSUBISHI CANTER	Policy No.	: 1001459124
Assignment Date	: 29/04/2022	Excess	: S\$700.00
Date of Inspection	: 29/04/2022	Est. Duration of Repair	: 0
Inspection At	: GOLDBELL ENGINEERING PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-24 SINGAPORE 628457		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	NOT READY
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	1,990.00

Salvage Value	:S\$	
Margin for Repair	:S\$	52,010.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
PENDING ESTIMATE FROM REPAIRER.