

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala

Date: 10 May 2022

Preliminary Advice

Vehicle No	: YP3896G	Accident Date	: 28/04/2022
Make	: MITSUBISHI CANTER	Policy No.	: 1001459124
Assignment Date	: 29/04/2022	Excess	: S\$700.00
Date of Inspection	: 29/04/2022	Est. Duration of Repair	: 15
Inspection At	: GOLDBELL ENGINEERING PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-24 SINGAPORE 628457		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 53,024.87
Revised Amount	:S\$ 44,790.93
Check Items (Estimated)	:S\$ 4,074.91
Total	:S\$ 48,865.84

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 54,000.00
COE / PARF Rebate	:S\$ 1,990.00
Salvage Value	:S\$

Margin for Repair

:S\$ 52,010.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to part prices and labour cost check.