



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 2 / 3

ESTIMATE

Date :	09/05/2022	Reg No :	YP3896G
To :	MSIG INSURANCE (SINGAPORE) PTE. LTD.	Model :	FEB21ER4SDEB CBU MT
Attn. :		Chassis No :	FEB21EA20506
Office / Mobile :		Engine No :	4P10C14791
Email Address :		Quotation No. :	155693
		Ref. No. :	
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	28/04/2022
Attn. :	HASRIANAH	Policy No. :	
Office / Mobile :		Claim Type :	
Email / Fax No. :	Hasrianah@goldbell.com.sg	Workshop :	8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	3600	6000.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK		180.00 ✓
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	2450	3500.00
4	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	600	700.00

LABOUR TOTAL :	10,380.00
SUB-TOTAL :	53,024.87
GST @ 7% for \$ 53,024.87	3,711.74
GRAND TOTAL (\$\$) :	56,736.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK) 29/4/22

OD - Not Authorise
Excess - ?

L/S

Resurvey After Spray
15

