



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE

HQ TRANSPORT COMMAND

KRANJI CAMP 3

151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA22004058/Epq2

Date: 06/02/2023

Code: MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 33769	Veh. Inspected	GBF 6284C
Policy No.	OA22008674	Coverage (\$)	0.00
Claim No.	CY 22/MID33769/160422/0017	Excess (\$)	0.00
Assign From		Assign Date	29/04/2022

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1MC2E26Z0007003	Colour	SILVER
Odometer	221701 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	4 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	4 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	4 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/04/2022	Inspection Date	25/05/2022
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6284C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILLAMP RH (N)	BROKEN	378.40	378.40
2	TAILLAMP GORMMET RH @\$5.70 (N)	NOT NECESSARY	11.40	-
1	REAR FENDER RH (N)	DENTED	2,026.60	2,026.60
1	REAR DOOR RH (N)	DENTED	1,711.70	1,711.70
1	REAR DOOR OUTER HANDLE RH (N)	NOT NECESSARY	210.10	-
	LESS 10% DISCOUNT		-433.82	-411.67
			3,904.38	3,705.03
	<u>LABOUR</u>			
	TO CUT & WELD REAR FENDER RH ,TO REPAIR REAR INNER PANEL RH .TO REMOVE & REFIX DAMAGED PARTS.STRAIGHTEN & REALIGN AFFECTED AREAS .		840.00	800.00
	TO SPRAY AFFECTED AREAS .		850.00	500.00
	TO REMOVE & REFIX DOOR MECHANISM ,CHECK & TEST WERE NECESSARY.		60.00	50.00
	TO RUST PROOF AFFECTED AREAS .		40.00	30.00
			1,790.00	1,380.00
	GRAND TOTAL		5,694.38	5,085.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,050.00

Report Ref No. CC2/MIDA22004058/Epq2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 6284C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 6284C

RE-INSPECTION

