

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF597T*Not Notified*
Presing B4 panel
AAD2204-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 APR 2022**SHF597T**

JTDKB3FU103093835

200303878K

TOYOTA

PRIUS GEN 4

28/04/2022

SLX5374U/AUTO&GEN

25/02/2021

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>Pr</i> 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>Pr</i> 22.00 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Pr</i> 374.50 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Pr</i> 132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Pr</i> 132.60 X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>Pr</i> 1,147.80 X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>Pr</i> 54.60 X
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>Pr</i> 54.60 X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>Pr</i> 47.90 X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>Pr</i> 913.60 X
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>Pr</i> 259.20 X
1	WEATHERSTRIP, BACK DOOR	\$	<i>Pr</i> 372.30 X
1	COVER, DECK TRIM, REAR	\$	<i>Pr</i> 126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>Pr</i> 651.00 X
1	STAY ASSY, BACK DOOR, LH	\$	<i>Pr</i> 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	<i>Pr</i> 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>Pr</i> 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>Pr</i> 61.00 X
TOTAL		\$	5,229.10
25%		\$	1,307.28
		\$	3,921.83

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

2 WINDSCREEN SEALANT

\$	<i>Pr</i> 700.00 X
\$	<i>Pr</i> 95.00 <i>600.00</i>
\$	<i>Pr</i> 150.00 X

Trans-cab Auto Services Pte Ltd

AAD2204-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF597T

1 WINDSCREEN MOULDING	\$	<i>pu</i> 200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>pu</i> 130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	<i>nn</i> 80.00	X
1 REAR TAILGATE STICKER "6555-3333"	\$	<i>nn</i> 80.00	X
1 REAR BUMPER PROTECTOR	\$	<i>pu</i> 180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	<i>nn</i> 85.00	X
1 END PANEL TRIM CLIP	\$	<i>nn</i> 65.00	X
1SET BUMPER CLIP FRT	\$	<i>nn</i> 95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>pu</i> 200.00	X
TOTAL	\$	2,060.00	

TOTAL PARTS \$ 5,981.83**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i> 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>nn</i> 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 480.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2204-

SHF597T

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Towing Fees	\$	nn	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	320%
To reinstall rear bumper parking sensor.	\$		170.00	50%
To Check Electrical Lighting Concerned.	\$	nn	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$	nn	170.00	X
To lift-up / out engine with gear box and refit.	\$	nn	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X

TOTAL \$ **10,290.00****Over All Total** \$ **16,271.83****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/04/2022 15:24 (SGT)
Date of Accident 28/04/2022 09:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG NEW UPPER CHANGI ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHF597T

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62876666
Alternative Phone No (Office) +65-62876666

VEHICLE PARTICULARS


Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1767

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number -

DRIVER

Name of Driver CHOW YIN KOK
NRIC No SXXXX257J



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
ANG QI HAO, VICTOR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20220428/2033

1 of 3

Report No. T/20220428/2033

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
28/04/2022 11:49

Vide Report No.:

Station Diary No.:
51

Informant's Particulars

Name of Informant:
CHOW YIN KOK

Address:
APT BLK 354 HOUGANG AVENUE 7 #03-701 SINGAPORE
530354

ID Type / ID No.:
NRIC NO / S1446257J

Contact No.:
Home/Office: Mobile: 81694162

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:
Male 61 01/07/1960

Type of Informant:
Driver

Race:
Chinese

Language:

Institution / School Name:

Occupation:
Taxi driver

Driving Licence Information:
Class: 2B,3

Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/04/2022 09:30	Type of Location: Straight Road
-------------------	---------------	-----------------	---	---------------------------------

Location:

NEW UPPER CHANGI ROAD

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
One Way

Traffic Control:
Traffic Light - Working

Traffic Volume:
Moderate

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHF597T	Car				Slightly Damaged	1
SLX5374U	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999



T/20220428/2033

2 of 3

Report No. T/20220428/2033

CONTINUATION OF REPORT

Driver		ID No.	S1446257J
Name	CHOW YIN KOK	Contact No.	81694162
Related Vehicle	SHF597T (Car)	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Hospital/Clinic	POW FAMILY CLINIC & SURGERY	Date Treatment	28/04/2022
Date Treatment	28/04/2022	Date Discharge	28/04/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 28/04/2022 at about 0930hrs, I was driving my taxi SHF597T ferrying a male passenger onboard travelling on the 2nd lane of New Upper Changi Road. At this juncture, my taxi is in stationary position just before the traffic light as it is showing red awaiting to turn green. Everything intact and in order.

Out of a sudden, I felt an huge impact from the rear of my taxi causing me and my passenger to jerked forward strongly. I took a moment to rest and compose myself in my taxi as I felt dizzy at that moment, while my passenger called for ambulance for me as he observe that I was not looking well. The driver of SLX5374U that collided from the rear of my taxi came forward to check on me and after some time I got out of my taxi to take picture of the accident and the rear portion of my taxi is damaged upon observation. The driver of SLX5374U then explained that the accident is his fault as a cockroach suddenly jumped onto his hands causing him a scare reaction hence he stepped on the accelerator pedal which caused the collision. After taking pictures of the accident, I manage to exchange contact details of the driver of SLX5374U and we decided to claim through insurance. The driver of SLX5374U and my passenger proceed to leave the scene while I continued waiting for the ambulance to arrive but after waiting for some time without a sign of ambulance I also proceeded to leave as well.

There is in-car camera installed in my taxi but I am unsure if the accident is recorded. No ambulance or TP at scene. I went to POW FAMILY CLINIC & SURGERY to make a check as I felt pain and discomfort on my lower and upper back portion and was given 3 days of MC (Certificate No.: MC/111547) from 28/04/2022 to 30/04/2022 by Dr Pow Chun Mei (M04329Z).

I am lodging this traffic accident report for insurance claims purpose. That is all.