



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref : WH1157					
Vehicle No. : SMN6024P				Page No. 1	
Make & Model : TOYOTA PRIUS PLUS (AUTO)					
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	Part Items Total:			
1	Bonnet		250.00		
1	Bonnet lock		70.00		
1	Front bumper logo badge		50.00		
1	Front bumper top rubber seal		40.00		
2	Front bumper side retainer LH/RH @2*\$45		90.00		
1	Front bumper sponge		70.00		
1	Front bumper reinforcement		180.00		
2	Headlamp LH/RH @2*\$800		1600.00		
1	Radiator top garnish		120.00		
1	Wiper top side garnish RH		35.00		
1	Front bumper		240.00		
1	Center grille		170.00		
1	Front bumper lower grille		190.00		
1	Bonnet hinge LH/RH @2*\$30		60.00		
1	Front Fender LH (Repair refer to labor)		0.00		
1	Front door LH (Repair refer to labor)		0.00		
1	Towing cover (Repair refer to labor)		0.00		
1	Support Panel (Repair refer to labor)		0.00		
</					



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 2

Our Ref	:	WH1157
Vehicle No.	:	SMN6024P
Make & Model	:	TOYOTA PRIUS PLUS (AUTO)

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	
Labour Total :		2060.00	
TOTAL (PARTS & LABOUR):		5681.50	