



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref : WH1157					
Vehicle No. : SMN6024P				Page No. 1	
Make & Model : TOYOTA PRIUS PLUS (AUTO)					
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>				
1	Bonnet ✓ BUC		250.00		
1	Bonnet lock ✓ BT		70.00		
1	Front bumper logo badge ✓ NEC		50.00		
1	Front bumper top rubber seal X NN		40.00		
2	Front bumper side retainer LH/RH @2*\$45 ✓ CUT		90.00		
1	Front bumper sponge X NN		70.00		
1	Front bumper reinforcement X NN		180.00		
2	Headlamp LH/RH @2*\$800 ✓ CRA		1600.00		
1	Radiator top garnish ✓ CRA		120.00		
1	Wiper top side garnish RH X NN		35.00		
1	Front bumper ✓ DE		240.00		
1	Center grille ✓ CRA		170.00		
1	Front bumper lower grille ✓ BR		190.00		
1	Bonnet hinge LH/RH @2*\$30 ✓ BT		60.00		
1	Front Fender LH (Repair refer to labor)		0.00		
1	Front door LH (Repair refer to labor)		0.00		
1	Towing cover (Repair refer to labor)		0.00		
1	Support Panel (Repair refer to labor)		0.00		
		Part Items Total:	10%	3165.00	
				316.50	
				3481.50	
<u>SPECIAL NETT ITEMS</u>					
1	Front bumper clips ✓ NEC		35.00		
1	Bonnet Insulator clips ✓ NEC		35.00		
1	Center grille clips ✓ NEC		35.00		
1	Front car plate with Holder ✓ CUT		35.00		
SN Items Total:			140.00		
Total Parts:			3621.50		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1157
Vehicle No.	: SMN6024P
Make & Model	: TOYOTA PRIUS PLUS (AUTO)

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	✓
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
Labour Total :		2060.00	
TOTAL (PARTS & LABOUR):		5681.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5 Days

Part by part

Before paint photos

Excess: TBA

Not Authorised

Guo Qiang - LKK

82880282

04/05/2022

GuoQiang@lkkauto.com